

ASS. REC. BY:

REF: SPF / 23002061/kwKenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No: SMC 644YYr Regn: 06.18Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: ToyC.C. 1598Colour: M.P. White

A/C: _____

Insured / Std / Nil / NA

Sp. Reading: 104428

T/Radio: _____

Insured / Std / Nil / NA

Eng/No: _____

C/No: NR053REH 604583449Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD / Rlm or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

Rear

R/Bal. 0 mmR/Bal. 0 mmL/Bal. 0 mmL/Bal. 0 mmD.O.A. 26/12/22D.O.I. 24/2/2023

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Transportation

S - RS, SI

: Firms

: Others

Report Format:

Lump Sum / I.B.I: (\$

TOTAL

VEHICLE NO: SMC644Y

MODEL: TOYOTA ALTIS

CHASSIS NO: MR053REH604583449

DESCRIPTION		REPAIRER'S ESTIMATE(\$\$)	
<u>PARTS (LIST ITEMS)</u>			
FRONT BUMPER		Br/100	\$ 500.00
FRONT BUMPER LOWER GRILLE		\$ P _h	300.00
FRONT GRILLE		\$ P _h	350.00
FRONT GRILLE EMBLEM		\$ A	100.00
FRONT REINFORCEMENT		\$	350.00
HEADLAMP LHS		W	\$ 1,250.00
		25%	\$ 2,850.00
			\$ 712.50
			\$ 2,137.50
<u>SPECIAL NETT ITEMS</u>			
FRONT BUMPER CLIPS			\$ M 60.00
	Total		\$ 60.00
	TOTAL PARTS		\$ 2,197.50

NOT Withair
11 Ry &
Merry After Party
2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 1,000.00	2001
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ 1,000.00	2201
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ 100.00	201
4	To provide anti-rust treatment on affected areas	\$ 100.00	X
	Labour Total :	\$ 2,200.00	
	TOTAL (PARTS & LABOUR):	\$ 4,397.50	