



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



AUTOMOBILE INSPECTION REPORT

INCOME INSURANCE LTD

Ref: NS/INC23002064/Snp3m4

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

Date: 24-03-2023

Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLE 9801C	Veh. Inspected	SHD 6811X
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1210554-002	Excess (\$)	0.00
Assign From		Assign Date	21/02/2023

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ	c.c	2143
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WDD2120012B309203	Colour	WHITE
Odometer	506588	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R16	GITI	5 mm
L/H Front Tyre	225/55 R16	GITI	5 mm
R/H Rear Tyre	225/55 R16	GITI	5 mm
L/H Rear Tyre	225/55 R16	GITI	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	19/02/2023	Inspection Date	21/02/2023
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------