

ASS. REC. BY: PLM

REF:

CS3/HSB2300 2672/Rnp3

0243

COE 2025/PLM

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: F2 10224at Workshop m/s EQUIPMENT EXTREMEof 4001, DEHOT LN #01-08Insured: HSBC

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 7K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: F2 10224 Yr Regn: 2005 / APR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda CB 400SF C.C. 399Colour: MULTI A/C: Insured / Std / NI / NASp. Reading: 228947 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JH 2MC39954M020069

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 110/70-17R: 150/70-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or TIMSUN

Front _____ Rear _____

R/Bal. 4 mm R/Bal. 5 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 07/02/23 D.O.I. 24/02/23Survey held at EQUIPMENT EXTREME

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt & O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 5-5K

ESTIMATE RANGE OF REPAIR / no. of days = (4K-5K) / 4 days

Date/Time, File Pass to?

☐ : Preli. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Photos _____

Others _____

TOTAL

Repaired/Former: _____

Lump Sum / L.B.A. / _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Inve (\$ _____)☐ : Weekend (\$ _____)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	024J
Vehicle Details	
Vehicle No.:	FZ1022Y
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Feb 2023
Vehicle Make:	HONDA
Vehicle Model:	CB400SF
Primary Colour:	Red
Manufacturing Year:	2004
Engine No.:	NC23E2064601
Chassis No.:	JH2NC39954M020069
Maximum Power Output:	-
Open Market Value:	\$8,311.00
Original Registration Date:	08 Apr 2005
First Registration Date:	08 Apr 2005
Transfer Count:	10
Actual ARF Paid:	\$1,247.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2025
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$4,853.00
COE Rebate Amount:	\$1,017.00
Total Rebate Amount:	\$1,017.00

Honda CB400 Super 4 Spec 3

Listing Type

Free Ad

Brand

Honda

Model

Honda CB400 Super 4 Spec 3

Engine Capacity

399cc

Classification

Class 2A

Registration Date

07/05/2005

COE Expiry Date

30/04/2025

(2yrs 2mths 4days COE left)

Mileage

290000km

No. of owners

7

Type of Vehicle

Street Bikes

SGD \$7300