

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI23002081/Awp3m4	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date:	18/04/2023	
			Code	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SME 9204P	Veh. Inspected	SLW 9644U	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10020553 /JL	Excess (\$)	0.00	
	Assign From	FRAULEINE KHOO	Assign Date	24/02/2023	
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI ELANTRA	c.c	1591	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	KMHD841CMJU646552	Colour	GREY	
	Odometer	56367 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	MICHELIN	6 mm	
	L/H Front Tyre	195/65 R15	MICHELIN	6 mm	
	R/H Rear Tyre	195/65 R15	MICHELIN	6 mm	
	L/H Rear Tyre	195/65 R15	MICHELIN	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	16/02/2023	Inspection Date	28/02/2023	
	Survey held at	CAS GARAGE PTE LTD			
		NO. 1 KAKI BUKIT AVE 6, #02-22 AUTOBAY 417883 KAKI BUKIT			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: