

PRS

## ASSIGNMENT

From: PRS Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: FD 6997S Yr Regn: 16/3/11  
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Yamaha PZ16 c.c. 153  
 Colour: Black A/C: Insured / Std / NI / NA  
 Sp. Reading: 14753 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: ME11C051A 707381  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modl: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 110/70-17  
 R: 180/70-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_

Front Rear  
 R/Bal. 4 mm R/Bal. 4 mm  
 L/Bal. \_\_\_\_\_ mm L/Bal. \_\_\_\_\_ mm  
 D.O.A. 22/1/22 D.O.I. 1/8/22  
 Survey held at Infinity  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
8 Rear RH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MR-6K</u> <u>Repair range 1K-2K</u> <u>3 days</u>
02/03/23	Submit LS \$1950, 4 days. (Red \$1650, 46%)

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 4

1) 02/03 Typist

☐ : Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS, \$ \_\_\_\_\_

Photos

Others

TOTAL

Repair Format: TPLump Sum 1950