

ASS. REC. BY:

REF:

A15/ 23002091/kp

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

854K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

CA days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

02/30

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMU 991A

Yr Regn:

03, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Sur Pwrt

c.c

1586

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

246581

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JSAEEC 31500204816

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/50R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

6

mm

L/Bal.

7

mm

L/Bal.

6

mm

D.O.A.

20/2/23

D.O.I.

23/2/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt o/s down

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/3 11/11/2023 8:140d Cabot

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS - SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 20051400L

ALLIANZ INSURANCE COMPANY OF SINGAPORE P/L
 79 ROBINSON ROAD
 #09-01 SINGAPORE 039190

Attention : Motor Claim Department
 Contact : 62972529 Fax No. : 62971956

Estimate : TP23/010

Date : 22/02/2023
 Vehicle Num. : SMU 991A
 Make/Model : SUZUKI SWIFT 1.6MT-2010
 Chassis/Eng# : JSAEZC31S00204816/M16A1483780
 Accident Date : 20/02/2023
 Claim No. :
 Reference : LYB/SMU991A/Allianz/TP/sl
 Policy No. :

Not Notified
1/1 Sing & 1400h
Resurvey After Paint
9 days

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|----|---|-----------------------------|--|--|
| 1. | 1 | LIST ITEMS : | | |
| 2. | 1 | FRONT DOOR/LH | | |
| 3. | 1 | FRONT DOOR OUTER HANDLE/LH | | |
| 4. | 1 | FRONT DOOR OUTER CHANNEL/LH | | |
| 5. | 1 | FRONT DOOR RUBBER/LH | | |
| 6. | 1 | FRONT DOOR INNER LOCK/LH | | |
| 7. | 1 | FRONT SIDE MIRROR ASSY/LH | | |
| | | FRONT DOOR INNER ROUND SEAL | | |

List TotalS\$:
 15.00% Discount S\$:

By	795.30	✓
By	138.00	✓
By	121.00	✓
By	198.00	✓
By	311.00	✓
By	455.00	✓
By	28.20	✓
	2,046.50	
	306.98	
	1,739.52	

- LABOUR :
- TO TRANSFER FRONT DOOR MECHANISM TO NEW DOOR
 - TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED PANELS
 - TO CHECK WATER SEEPAGE
 - TO SUPPLY & REPLACE FRT & REAR DOOR AFFECTED STICKER
 - TO REPAIR, PANEL BEAT, ALIGN ON AFFECTED AREA & LABOUR
 - TO REPLACE ABOVE PARTS

	120.00	601
	60.00	301
	300.00	2001
	600.00	2001

CONTINUE / ...

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 20051400L

ALLIANZ INSURANCE COMPANY OF SINGAPORE P/L
 79 ROBINSON ROAD
 #09-01 SINGAPORE 039190

Attention : Motor Claim Department
 Contact : 62972529 Fax No. : 62971956

Estimate : TP23/010

Date : 22/02/2023
 Vehicle Num. : SMU 991A
 Make/Model : SUZUKI SWIFT 1.6MT-2010
 Chassis/Eng# : JSAEZC31S00204816/M16A1483780
 Accident Date : 20/02/2023
 Claim No. :
 Reference : LYB/SMU991A/Allianz/TP/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO PUTTY, PRIMER & SPRAY PAINT ON LFET FRT SIDE MIRROR, FRONT DOOR & REAR DOOR USING 2K PAINT		700.00
		Labour Total S\$:		1,780.00

4501

E. & O.E.

Total S\$: 3,519.52
 =====



for LIM YEW BOO SPRAY PAINT CO.