

RECEIVED: 20/7/09 REF: ALC

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
To Inspect Vehicle No: _____
Workshop No: _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
DAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Turn Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS WR
Date: _____ Person Contacted: Ms Lowe Vehicle: IN / OUT

Veh No: SH 65 98K Yr Regn: 20/7/09
Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Toyota Prius C.D. 1798
Colour: Blue A/C: Insured / Std / NI / NA
Sp. Reading: _____ T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: STD KB3 F4X03563795
Gen. Cond: 6 / Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brakes: In order / Jammed / Leaked / Burnt or
Modi: G / R / S / Rim / STD A/Rim or
Tyre Size: F: 195/65K15
R: 1 -
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO, or Washlake
Front: _____ Rear: _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 27/2/23
Survey held at Comfort Lodge
Des. of Damages: Frit Rear / O/S / W/S / U/C / Rooftop or
Front o/s.
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Prel. Report
Date/Time, File Return to? ☐ : Final Report

Days Of Repair: _____
Resurvey No. of Trip: _____
Survey Fees: _____
Transportation: _____
Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Traffic (\$)

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SH6598K

Make : Toyota

Model : Prius

Date: 23/02/2023

Insurance: ALLIANZ

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRONT FENDER SUB ASSY RH			\$ 1,111.93
1	FRONT FENDER HYBRID EMBLEM RH			\$ 86.50
1	FRONT FENDER SHIELD RH			\$ 198.50
1	FRONT BUMPER COVER			\$ 586.18
1	FRONT BUMPER SIDE BRACKET RH			\$ 82.30
10	FRONT BUMPER CLIPS			\$ 22.00
SUB TOTAL				\$ 2,087.41
LESS 25%				\$ 521.85
DISCOUNTED TOTAL				\$ 1,565.56
				\$ -
Labour Charge				
PANEL BEATING				\$ 750.00
SPRAY PAINTING CHARGE				\$ 600.00
TUFF KOTE				\$ 60.00
TOTAL LABOUR				\$ 1,410.00
ESTIMATE TOTAL				\$ 2,975.56

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanphin 97495749
 'wp' 27/2/23 @ 430
 L/S Resurvey after repair
 2 days
 Tanphin @ 11:00am

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 23.02.2023 16:04

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5886994

JC NO305546534

STOMER

/MS COMFORT TRANSPORTATION PTE LTD

STOMER NO. 7010045

DRESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755

(R) (O)

(P)

COUNT CARD NO.

REGN NO.:

SH 6598K

MILEAGE

MAKE:

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4)23.02.2023 14:20

DATE/TIME IN

YR OF MANU.

07.09.2017

TARGET DATE

CHASSIS CODE

JTDKB3FUX03563795

COMPLETION DATE/TIME:

Accident Date: 23.02.2023

ATURE: 3P 23.02.2023


JOB DESCRIPTION

S/NO

LABOR CODE

DESCRIPTION

FRONT



CKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

Exit Pass

No.: SH 6598K

YY

Vehicle No.:

SH 6598K

Signature/Date

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard