

4RENSIC MOTORS PTE LTD

8 KAKI BUKIT AVEUNE 4 #01-50 PREMIER @ KAKI BUKIT SINGAPORE 415875

Vehicle number: SKK3448J
 Make and model: Toyota Estima
 Chassis number: ACR500160325
 Registration Year: 2013

No.	Parts	Qty	Remarks	Amount S\$
1	Tailgate	1		\$ x 1,958.60
2	Tailgate windscreen glass rubber moulding	1		\$ x 181.00
3	Tailgate centre emblem	1		\$ x 78.00
4	Tailgate "Estima" emblem	1		\$ x 106.00
5	Tailgate "AERAS" emblem	1		\$ x 87.00
6	Tailgate LH lamp assy	1		\$ x 453.00
7	Rear bumper	1		\$ de 748.50
8	Rear bumper clips	1set		\$ 304 80.00
9	Rear bumper LH side retainer	1		\$ de 78.10
10	Rear bumper LH corner side bracket	1		\$ de 76.30
11	Rear bumper LH reflector	1		\$ act 83.30
12	Rear bumper LH inner sponge	1		\$ any 101.10
13	Rear LH fender	1		\$ bt 1,192.70
14	Rear LH fender lower protector	1		\$ x 317.80
15	Rear LH fender lower protector clips	1set		\$ x 28.00
16	Rear LH fender glass with rubber moulding	1		\$ x 1,166.20
17	Rear LH fender splash shield	1		\$ x 231.50
18	Rear LH fender splash shield clips	1set		\$ x 70.00
19	Rear LH fender inner trim board	1		\$ x 967.80
20	Rear LH fender inner trim board clips	1set		\$ x 80.00
21	LH taillamp assy	1		\$ any 606.30
22	LH taillamp panel	1		\$ x 173.20
23	LH taillamp lock clips	1set		\$ x 70.00
24	Rear LH chrome sport rim	1		\$ x 1,332.00
25	Rear LH wheel bearing	1		\$ x 1,427.20
26	Rear LH shock absorber	1		\$ x 385.40
27	Rear axle beam	1		\$ x 3,752.10
28	LH rear sliding door	1		\$ x 2,095.40
29	LH rear sliding lower protector	1		\$ x 817.70
30	LH rear sliding lower protector clips	1set		\$ x 85.00
31	LH rear sliding door lock with motor 1337.4	1		\$ x 1,337.40

Reverse sensor in - \$200

Parts Sub Total: \$ 20,166.60
 Less 25%: \$ 5,041.65
 Parts Total: \$ 15,124.95

No.	Special Nett	Qty	Remarks	Amount S\$
1	Rear LH fender glass sealant	1		\$ 400 80.00
2	Rear LH fender glass inner seal	1		\$ 304 60.00
3	Rear LH fender joint sealant	1		\$ 400 80.00
4	Rear LH tyre	1		\$ x 580.00
5	Brake fluid	1		\$ x 85.00
	Tailgate windscreen glass sealant	1		\$ x 80.00
	Tailgate windscreen glass inner seal	1		\$ x 60.00

Special nett total: \$ 1,025.00

No.	Labour, painting and misc	Amount S\$
1	Labour charges on affected and consistent areas and panels	\$ 700 1,600.00
2	Putty and re-spray on affected areas and panels	\$ 700 1,400.00
3	Check wiring and lighting system	\$ 30 80.00
4	Spray anti rust chemical on affected areas	\$ 30 100.00
5	Remove and reinstall rear bumper reverse sensors to assist repair	\$ 30 100.00
6	Remove and reinstall rear inner trims, garnish and boards to assist repair	\$ 60 380.00
7	Remove and replace rear LH fender glass to assist repair	\$ 60 220.00
8	Remove and replace roof lining, seats and carpet to assist repair	\$ 60 580.00
9	Test drive and adjust wheel alignment system	\$ X 180.00
10	Remove and replace rear undercarriage parts to assist repair	\$ X 500.00
11	Remove and replace LH sliding door inner mechanism to new door	\$ X 120.00
12	Remove and reinstall tailgate windscreen glass to assist repair	\$ X 250.00
13	Remove and reinstall tailgate inner mechanism to new tailgate	\$ X 12.00
14	Remove and reinstall tailgate reverse camera to assist repair	\$ X 100.00
Labour total:		\$ 5,622.00

Tanpin 9744545
 WP 27/12/23 & 3pm
 4/5 hours after repair
 Tanpin (Khantun)
 6 days
 - To check consistency of accident
 - To check part prices

Parts total: \$ 15,124.95
 Special nett total: \$ 1,025.00
 Labour total: \$ 5,622.00
 Grand total: \$ 21,771.95

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 996D

Vehicle Details

Vehicle No.: SKK3448J
Vehicle to be Exported: Yes
Intended Deregistration Date: 24 Feb 2023
Vehicle Make: TOYOTA
Vehicle Model: ESTIMA AERAS 2.4 A
Primary Colour: Black
Manufacturing Year: 2013
Engine No.: 2AZH974369
Chassis No.: ACR500160325
Maximum Power Output: 125.0 kW (167 bhp)
Open Market Value: \$31,986.00
Original Registration Date: 28 Jun 2013
First Registration Date: 28 Jun 2013
Transfer Count: 1
Actual ARF Paid: \$36,781.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 27 Jun 2023
PARF Rebate Amount: \$18,390.00

Intended COE Rebate Details

COE Expiry Date: 27 Jun 2023
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$73,301.00
COE Rebate Amount: \$2,504.00
Total Rebate Amount: \$20,894.00

The information contained herein is correct as at 24 Feb 2023

OK

Date of Accident : 22/02/2023 Accident Time: 0715hrs (24-HR-FORMAT)
Accident Place : Bartley Road East
Vehicle Reg. No (Car plate No.) : SKK34483 CC : 2-4A
Insurance Company : FWD Vehicle Make/Model: Toyota Estima
Name of Registered Owner : Company / Individual Lam Hong Kin Policy No. PNPV2022-00003110
ID of Registered Owner : Co Reg No: Owner's NRIC No: S79709960
OWNER EMAIL ADDRESS: kinlam@singnet.com.sg : Co Contact No: Owner's Contact No: 96584798
DRIVER'S Name : Lam Hong Kin DRIVER'S NRIC No: S79709960
DRIVER'S Date of Birth : 27/05/1979 DRIVER'S License Pass Date 18/03/1999
Relationship bet. Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: Owner
DRIVER'S Address : 104A Bidadari Park Drive #16-75 S(341104)
DRIVER'S Contact No./ Alt No. : 1) 96584798 2) _____
DRIVER'S Occupation : INDOOR \ OUTDOOR (eg. working inside or outside of an ofc)
Email Address : kinlam@singnet.com.sg
Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET
Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance
Number of Passengers (including Driver): 01 Name & Gender: Lam Hong Kin / Male
Was the accident reported to the police? YES \ NO
Was there any video Captured by car camera: YES \ NO
Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose
Any injuries, if yes (name of the injured person) _____

Other Party Driver's Particulars (if any)

Vehicle Reg No: <u>CB 7039Y</u>	Vehicle Reg No: _____
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name DRIVER: _____	Name DRIVER: _____
IC No. DRIVER: _____	IC No. DRIVER: _____
DRIVER'S Contact & add: _____	DRIVER'S Contact & add: _____

REPORT FORM EXPLAINED IN : ENGLISH / CHINESE / MALAY / TAMIL OTHERS: _____
WHO REPORTED THE ACCIDENT : OWNER / DRIVER / BOTH _____

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Actual Driver.
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
 6. This report will be forwarded by the Insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
6. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and consent that:
- (e) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VC 22 Feb 23
Policyholder's Signature / Date & Time

VC 22 Feb 23
Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan



Describe Circumstance of the Accident

On the stated time and date, I was travelling straight on the stated location. As the traffic slowed down, I followed suit and came to a stop eventually as the traffic was heavy. Suddenly I felt a huge impact from my rear of my vehicle. I alighted and found out Vehicle B 'CB7039Y' cut across the chevron marking changing into my lane behind me causing the collision causing damages to my vehicle.

Declaration

I/We declare the foregoing particulars are true in every respect.

10: 22 Feb 23

Policyholder's Signature / Date & Time

10: 22 Feb 23

Driver's Signature (if driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel