

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 19960/198R GST Reg. No. 19-960/198-R						
Affiliated to Federation Internationale Des Experts En Automobile						
	MS FIRST CAPITA	AL INSURANCE LTD	Re	f: (	CS/FCI23002151/Uwy3e2	
	16 RAFFLES QUA #42-01 HONG LEC SINGAPORE 0485	ONG BUILDING	Da	ite: 2	20/03/2023	
			Co	de: F	FCI2	
1.						
	Insured Veh.	YP 7830U	Veh. Inspected	(	GBD 784B	
	Policy No.	D22099240	Coverage (\$)		0.00	
	Claim No.	D23000702MFCV	Excess (\$)	(	0.00	
	Assign From	AINI BINTE	Assign Date	2	27/02/2023	
2.	2. Vehicle Particulars & Condition					
	Make & Model	NISSAN NV200 (A)	c.c	1	1597	
	Engine No.	HIDDEN	Year of Reg.	2	2014	
	Chassis No.	VM20055456	Colour	(	GREY	
	Odometer	223930 KM	Steering	I	N ORDER	
	Brakes	IN ORDER	Modification	1	NIL	
	General	GOOD				
3.	. Conditions of Tyres					
		Size	Make	E	Balance	
	R/H Front Tyre	175/70 R14	HABILEAD	6	3 mm	
	L/H Front Tyre	175/70 R14	HABILEAD	6	3 mm	
	R/H Rear Tyre	175/70 R14	HABILEAD	6	3 mm	
	L/H Rear Tyre	175/70 R14	HABILEAD	6	3 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	22/02/2023	Inspection Date	2	28/02/2023	
	Survey held at	SAM YICK LIAN				
		1, KAKI BUKIT AVE 6 #01-70 SINGAPORE 417883				
5a.	Remarks					
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

**6 Working Days** 

ESTIMATED NORMAL PERIOD FOR REPAIR: