

(08/11/13) wef

ASS. REC. BY: form

REF: CS3/HBB23002183/Rq3

oscu

600-2024/mar

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBC 777C

at Workshop m/s KOH KOK LEONH

of 24 TWS BVE 2

Insured: HSBC

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: DK

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBC 777C Yr Regn: 2009 / MAY

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: LAND ROVER DEFENDER 90 2004 c.c 2402

Colour: GREEN A/C: Insured / Std / NI / NA

Sp. Reading: 301214 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SALLDVAS 79A 768842

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 265 / 75R16

R: 62

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

TRIANGLE

Front

Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 25/02/23 D.O.I. 01/03/23

Survey held at KKL

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRT O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 9K

ESTIMATE RANGE OF REPAIR / NO. OF DAYS - 2K-3K / 5 days

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

) S + RS. \$

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	084W
Vehicle Details	
Vehicle No.:	GBC777C
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Mar 2023
Vehicle Make:	LAND ROVER
Vehicle Model:	DEFENDER 90 2.4L PUMA
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	080818121021244DT
Chassis No.:	SALLDVA579A768842
Maximum Power Output:	-
Open Market Value:	\$40,750.00
Original Registration Date:	31 Mar 2009
First Registration Date:	31 Mar 2009
Transfer Count:	0
Actual ARF Paid:	\$2,038.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Mar 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$13,378.00
COE Rebate Amount:	\$2,855.00
Total Rebate Amount:	\$2,855.00