

ASS. REC. BY:

REF:

CS/HLA23002195/Sny3

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TPRES/ODRES/EVA/INV/INV

To Inspcd Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: HLA

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent: Yes or No

GIA / PR Secur: \_\_\_\_\_ Consistent: Yes or No

Est. Repairs: 2 days Res: Yes or No

Lump Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN/OUT

Veh No: Shd 682LS Yr Reg: 08/14/2016

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Mercedes Benz 'cc 2143Colour: White

AC: Insured / Std / NI / NA

Sp. Reading: 882326

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/Nr: WDD2120072B309369Gen. Cond: Good / Fair / Poor / BurntSteering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt orMod: NI / S/Rm / STD / Affm, orTyre Size: F: 225/55 R16  
R: \_\_\_\_\_

BS/DUN/EXNOVA/GY/FS/LZA/WIC/OHTSU/PR/SUMI/

TOYO/YOKO or Grifi

Front

Rear

R/Bal: 5 mmR/Bal: 5 mmL/Bal: 5 mmL/Bal: 5 mmD.O.A. 16/2/23D.O.L. 1/3/23 3pmSurvey held at ComfortDes. of Damages: Front / Rear / O/S / N/S / W/C / Rooftop orRear O/S

The W/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PIP = 680Irfan confirmed final fig \$680 and 2 days  
(red. \$1508.69%)

Date/Time, File Pass to?

1) 28/03/23

Date/Time, File Return to?

2) \_\_\_\_\_

Report Format: TPLump Sum / LBJ: (\$) 680Days Of Repair: 2Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation

S + RS \$

Photos

Others

TOTAL



Date/Time: 27.02.2023 16:17

Page : 1

Job: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 5887399

JC NO305546685

Customer

IS COMFORT TRANSPORTATION PTE LTD

OMER NO. 7010045

ADDRESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717

(P) 65508755

(O)

(P)

Job Card No.

REGN NO: SHD6821S	MILEAGE
MAKE: MERCEDES BENZ	FUEL E 1/2 F
MODEL: E220CDI (E6)	DATE/TIME IN 27.02.2023 15:40
YR OF MANU. 08.04.2016	TARGET DATE
CHASSIS CODE WDD2120012B309369	COMPLETION DATE/TIME

## JOB DESCRIPTION


Incident Date: 16.02.2023

Incident Time: 3P 16.02.2023

Job No

LABOR CODE

DESCRIPTION



Job Card & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Job Card

Exit Pass

Job No: SHD6821S

YY

Vehicle No.:

SHD6821S

Service Advisor

Signature/Date

Name of Service Advisor

Date

Job Card to be kept by Security Guard

To be kept by Security Guard

## ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300



TP INSURER:  
CTPL

HL Assurance Pte Ltd (HQ)

Singapore

Loke Wei Yiong

### PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	16/02/2023
Vehicle Reg. No.:	SHD6821S	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	MERCEDES-BENZ 220E, 2.2 (A)	Vehicle Reg. Date:	08/04/2016
Vehicle Colour:	WHITE	Chassis No:	WDD2120012B309369
Engine No:	65192433225837		
Odometer:	882326 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Remarks:	TEL: 62148355		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	1,308.00
Miscellaneous Items	0.00
Labour	880.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>2,188.00</b>
<b>+ GST 8.00% (S\$)</b>	<b>175.04</b>
<b>Nett Amount (S\$)</b>	<b>2,363.04</b>

This claim is handled by: MS. LOKE YY

Generated using Merimen e-Claims Internet Estimation & Adjusting System