

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/EG/23002199/4wy3**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: G3H/89237at Workshop m/s 2nd Ave.

of _____

Insured: GSA 2981B

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: \$ 73k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 4 days

Res.: Yes or No

Lump Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

C6 P6k

Date: _____

Person Contacted: LIA 13624

Vehicle: IN / OUT

Veh No: G3H/89237 Yr Regn: 29/10/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (m)Make: Toyota Dyna C.C. 2982Colour: Orange A/C: Insured / Std / NI / NASp. Reading: 167377 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFAT35YXOK211 696Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195-215R: 155-213 Double King

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kapsen

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 12/02/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

29/13k

9/3/23 1/5 \$3000 inward AM/ary @ 04 days (Red \$6,080.00 / 67%)

Date/Time, File Pass to?

10/03/20231) Typist

Date/Time, File Return to?

2) _____

☐

: Preli. Report

☒

: Final Report

Days Of Repair: 04

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

) S + RS \$ _____

) Photos

) Others

TOTAL

Report Format: TPLump Sum / I.B.I. (\$ 45 \$3000)

VEHICLE NO. GBH 8923T

TOYOTA DYNA

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Front bumper <i>n</i>		1250.00	X
2	Front bumper bracket <i>n1</i>		160.00	X
1	Front centre panel upper <i>DD/Bent</i>		<i>648.10</i> 1128.00	—
1	Front centre panel <i>n</i>		782.00	X
1	Front lower panel <i>NS</i>		540.00	X
1	Front lower grille <i>n1</i>		192.00	X
2	RHS & LHS Headlamp @ 782 <i>hol/bur cre</i>		1564.00	—
2	RHS & LHS Sidelamp @592 <i>NS</i>		1184.00	X
1	Front centre grille <i>Cre</i>		598.00	—
			7398.00	
		less 25%	1849.50	25%
			5548.50	
SPECIAL NETT ITEMS				
1set	Front windscreen wiper	REFIX <i>n1</i>	0.00	X
2	Front windscreen water spray nozzle	REFIX <i>n1</i>	0.00	X
1	Front windscreen moulding	<i>n1</i>	378.00	X
1	Front number plate	<i>n1</i>	75.00	X
1	Front DYNA emblem	<i>neu</i>	98.00	<i>60</i>
1	Front centre panel company sticker	<i>neu</i>	150.00	✓
1 <i>of</i>	Front centre grille clips	<i>neu</i>	60.00	<i>40</i>
1	Front centre panel Badge	<i>n1</i>	72.00	X
Total Parts			6381.50	

not Authorised
her
1/3/23
L1 \$3000
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-2810.10
253
2107.57
250
1400
3757.57

VEHICLE NO. GBH 8923T TOYOTA DYNA

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	1200.00	580
2	To respray front portion (including repaired areas)	1200.00	800
3	To remove and re-fix wiring and check all electrical components and focus headlamp beam	120.00	20
4	To provide anti-rust treatment on affected areas	180.00	11X
	Labour Total :	2700.00	
	TOTAL (PARTS & LABOUR):	9080.00	

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	13/02/2023 17:30 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	12/02/2023 07:50 (SGT)
Exact Location of Accident	19 Admiralty St, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH8923T
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	ALPINE BUILDERS PTE LTD
Company Reg No	200515686K
Email Address	ANDREAHOI@SFLEASING.COM.SG
Mobile Phone No	(Phone) +65-97668811
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Dyna
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	3000

INSURANCE COMPANY

Name of Insurance Company	Allianz Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number	SF2003250730

DRIVER

Name of Driver	ISLAM MD SANIFUL
NRIC No	G6718260Q
Date Of Birth	01/01/1987
Occupation	Outdoor

Date, Of Driving Pass	26/10/2015
Driving experience	7 YEARS AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-91693688
Alt. Phone Number	-
Email Address	SAIFUL331611@GMAIL.COM
Address	19A ADMIRALTY STREET
Address complement	-
Postcode	756937
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head on collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Geylang Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18008486999
Alt. Police Station Phone No	(Fax) +65-68486799
Police Station Address	1 Cassia Link Singapore 397618
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT: T/20230213/2056.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number	GBA2931B
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-

Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	VEHICLE B
No. Of Passenger (Including Driver)	1

99 Circumstances of the Accident

At the stated date, time and location, my vehicle was parked with no one in the vehicle. I was walking to my vehicle and saw vehicle B enter into the front portion of my vehicle. The driver refused to stop and drove away.

Declaration

I declare the foregoing particulars are true in every respect.



Insured's Signature / Date & Time

[Handwritten Signature]

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Agent
(if required)

Printed Name: Company Name

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	686K
Vehicle Details	
Vehicle No.:	GBH8923T
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Mar 2023
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	1KD2828105
Chassis No.:	JTFAT35YX0K211696
Maximum Power Output:	-
Open Market Value:	\$27,082.00
Original Registration Date:	29 Oct 2018
First Registration Date:	29 Oct 2018
Transfer Count:	0
Actual ARF Paid:	\$1,355.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Oct 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$24,089.00
COE Rebate Amount:	\$13,624.00
Total Rebate Amount:	\$13,624.00

The information contained herein is correct as at 01 Mar 2023

OK

Post an Advertisement
 Sell it yourself! Advertise it at just
\$68 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Low Interest Rate In-House Loan by GV Cars Financing



80 Downpayment 90% Loan by
 GV Cars Financing at 3.28% p.a.
 Low Interest Rate
 GV Automobile Centre [StarAd](#)

Lake View Credit Pte Ltd
[view our cars](#)

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Sort by results/page

8 vehicles










TOYOTA DYNA

Any Category

Advanced Search



Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	TOYOTA DYNA		Any	Any	2018	Any	Any	Any	Available
	Toyota Dyna 150 3.0M		<u>\$78,800</u>	\$14,090 /yr	03-Oct-2018	2,982 cc	-	Truck	Available
	Fuel Type: Diesel								
	Own by one meticulous owner! Cheapest in the market! Excellent drive off condition. No repair needed. Full checker plate. New paint work. High loan available, high trade in value quote. Call now for viewing and test drive.								PREMIUM AD
	Lek Auto Pte Ltd								
	Posted: 27-Feb-2023								
	Toyota Dyna 150 3.0M		<u>\$79,800</u>	\$14,380 /yr	17-Sep-2018	2,982 cc	-	Truck	Available
	Fuel Type: Diesel								
	1 owner, well maintained, no repair needed, 100% loan available, call for appointment now!								
	ABWIN (1994) Pte Ltd								
	Posted: 24-Feb-2023								
	Toyota Dyna 150 3.0M		<u>\$78,800</u>	\$15,000 /yr	01-Jun-2018	2,982 cc	-	Truck	Available
	Fuel Type: Diesel								
	ENGINE & GEARBOX IN TIP-TOP CONDITION! Almost Like New! Brand New Paint! Super Well Maintained By Previous Owner! Low Genuine Mileage! Extra Engine & Gearbox Warranty Coverage! Full Loan/Cash Welcome! Trade In Welcome! Fast Loan Approvals! Kindly...								PREMIUM AD
	Car (S) Pte Ltd								
	Posted: 20-Feb-2023								
	Toyota Dyna 150 3.0M		<u>\$78,800</u>	\$13,890 /yr	01-Nov-2018	2,982 cc	100,416 km	Truck	Available
	Fuel Type: Diesel								
	Rare 2018 Toyota Dyna + box unit! Low mileage! Guaranteed smooth engine and gearbox! Class 3 can drive! 100% loan available! Accept trade in for any of your existing vehicle! Call us now for instant view / test drive!								PREMIUM AD
	ABS Bus Pte Ltd								
	Posted: 18-Feb-2023								
	Toyota Dyna 150 3.0M		<u>\$72,800</u>	\$13,980 /yr	15-May-2018	2,982 cc	89,980 km	Truck	Available
	Fuel Type: Diesel								
	Only one careful owner, new paintwork no repair needed high trade in and loan available.								
	Posted: 09-Feb-2023								
	Toyota Dyna 150 3.0M		<u>\$74,800</u>	\$14,050 /yr	26-Jun-2018	2,982 cc	-	Truck	Available
	Fuel Type: Diesel								
	1 Owner Only! Fully Agent Maintain. Full Checker Plate With Sliding Canopy. Call Now For Viewing/test drive. Trade In Are Welcome. Kindly Contact Our Friendly Sales Consultant.								
	Posted: 08-Feb-2023								
	Toyota Dyna 150 3.0M		<u>\$70,888</u>	\$14,370 /yr	05-Feb-2018	2,982 cc	122,300 km	Truck	Available
	Fuel Type: Diesel								
	1 owner only. Tip top engine and gearbox condition! No repair needed.								
	Posted: 26-Jan-2023								

[Compare](#)