

RECEIVED: *[Signature]*

INC

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
ID / TP / VS / TP RES / OD RES / EVA / INV / MV
o Inspac/Vehicle No: _____
Workshop No: _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remarks: The veh had commenced its repair at the time of inspection.

N/S	O/S
	☒

Est. or Market Value: _____
IDAC Accident Report: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS *WP'*

Date: _____ Person Contacted: *Ms Whe* Vehicle: IN / OUT

Date / Time	Action / Instruction

Veh No: *SHC 2935D* Yr Regn: *2019 Jan.*
Type: M.Car / M.Cycle / Bus / Van / Lorry / Truck / Prime Mover /
Truck / Trailer or
Make: *Toyota Prius* C.C. *1798*
Colour: *Blue* A/C: Insured / Std / NI / NA
Sp. Reading: *316803* T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: *5T0KR33F4803077938*
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Mod: UB / S/Rim / STD A/Rim or
Tyre Size: F: *195/65R15*
R: *20*
BS / DUN / EXNOVA / BY / PS / LIZA / MIC / DHTSU / PIR / SUMI /
TOYO / YOKO *Westlake*
Front: _____ Rear: _____
R/Bal. *6* mm R/Bal. *6* mm
L/Bal. *6* mm L/Bal. *6* mm
D.O.A. _____ D.O.I. *28/2/23*
Survey held at *Comfort Lodge*
Des. of Damages: Frit Ret / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to? ☐ : Prel. Report
1) ☐ : Final Report
Date/Time, File Return to?
2) _____
Report sent to: _____
Lump Sum / L.S. A: _____

Days Of Repair: _____
Resurvey No. of Trip: _____ Survey Fee: _____
Transportation: _____
Add Fee: ☐ : Site Insp \$ _____
☐ : Interview \$ _____
☐ : Tech. Chk \$ _____

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC2935D

Make : Toyota

Model : Prius (G4A)

Date: 27/02/2023

Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount	
1	REAR BUMPER			\$ <i>Rx</i> 503.04	
10	REAR BUMPER CLIPS			\$ <i>ne</i> 22.00	
1	REAR BUMPER LOWER COVER			\$ <i>de</i> 654.96	
1	REAR BUMPER REINFORCEMENT			\$ <i>?</i> 378.32	
1	BACK DOOR GARNISH SUB ASSY			\$ <i>sur</i> 1,054.71	
1	REAR TRUNK LID LOGO (PRIUS)			\$ <i>na</i> 62.14	
1	REAR TRUNK LID LOGO (HYBRID)			\$ <i>ne</i> 62.14	
1	REAR TRUNK LID LOGO (TOYOTA STAR)			\$ <i>ne</i> 81.43	
1	REAR TRUNK LID COVER			\$ <i>?</i> 1,303.29	
1	REAR WINDSCREEN GLASS WITH MOULDING			\$ <i>?</i> 1,884.32	
1	REAR TRUNK LID GLASS			\$ <i>ena</i> 1,569.70	
1	REAR SPOILER			\$ <i>Rx</i> 1,787.79	
1	REAR BUMPER TOWING COVER			\$ <i>x</i> 98.80	
	SUB TOTAL			\$ 9,462.64	
	LESS 25%			\$ 2,365.66	
	DISCOUNTED TOTAL			\$ 7,096.98	
	REAR BUMPER RUBBER MAT			\$ <i>?</i> 50.00	
	REAR TRUNK LID COMFORT & TEL NO. STICKER		-10%	\$ <i>ne</i> 60.00	Nett
	REAR TRUNK LID APPS STICKER		-10%	\$ <i>ne</i> 40.00	Nett
	REAR REVERSE SENSOR		-10%	\$ <i>ne</i> 135.70	Nett
				\$ 285.70	Nett
	Labour Charge				
	PANEL BEATING			\$ 1,050.00	525
	SPRAY PAINTING CHARGE			\$ 800.00	500
	REMOVE/ REFIX REAR WINDSCREEN GLASS			\$ 120.00	-
	TUFF KOTE			\$ 80.00	30
	REMOVE/REFIX REVERSE SENSOR			\$ 60.00	30
	TOTAL LABOUR			\$ 2,110.00	
	ESTIMATE TOTAL			\$ 9,492.68	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97495749
 "wp" 28/2/23 0330
 2/3 rising after repair
 3 days
 Tanpin 97495749
 01/03/2023

Link Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 28.02.2023 08:29

Page : 1

Job: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5887467

JC NO305546688

CUSTOMER

REGN NO:

SHC2935D

MILEAGE

AS COMFORT TRANSPORTATION PTE LTD

CUSTOMER NO. 7010045

ADDRESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

(R) 65508755

(O)

(P)

MAKE:

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4)/27.02.2023 15:40

DATE/TIME IN

YR OF MANU.

07.01.2019

TARGET DATE

CHASSIS CODE

JTDKB3FU803077938

COMPLETION DATE/TIME:

QUANTITY CARD NO.

JOB DESCRIPTION

Accident Date: 27.02.2023


ATURE: 3P 27.02.2023

/NO

LABOR CODE

DESCRIPTION

FRONT



REAR

LEFT SIDE

RIGHT SIDE

RECEIVED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Signature Slip

Exit Pass

No.: SHC2935D

YY

Vehicle No.:

SHC2935D

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard