ASS. REC. BY: Kenneth

REF: HSB/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s BCC

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: $

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 07 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SCZ 8877L Yr Regn: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or (A) Wagon

Make: Opel Astra eco C.C

Colour M. Green A/C: Insured / Std / NI / NA

Sp.Reading — T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WOLBE8EA9H8057562

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modl: NII / S/Rim / STD A/Rim or _____

Tyre Size: F: B.S 225/45R17

R: Dayton

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front		Rear	
R/Bal.	2 mm	R/Bal.	3 mm
L/Bal.	2 mm	L/Bal.	3 mm
D.O.A.	1/12	D.O.I.	1/3/2023

Survey held at _____ 3.45pm

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
/	Bottom Plate, PRS, no documents given
	En route con $12-14K

Time, File Pass to? _____ ☐ : Preli. Report ☐ : Final Report

Time, File Return to? _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____) ☐ : Interview ($ _____) ☐ Tech Invs ($ _____) ☐ Weekend ($ _____)

Survey Fee: _____

Transportation: $ - RS. ___ SI

Photos

Others

TOTAL

Format :

Sum / I.B.I: ($ _____)