

ASS. REF. NO. Tough

REF:

CS/CT/2300229/Twp 3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 91250

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 72K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNIA54246 Yr Regn: 2017, Feb

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 216D c.c. 1496

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA 213320V 925793

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoperative / Jammed / Leaked / Burnt or

Brake: Inoperative / Jammed / Leaked / Burnt or

Modi: NIL / S/Rim / STD A/Rim or

Tyre Size: F: 225/45 R17

R: 225/45 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 01/02/23

Survey held at Century Auto

Des. of Damages Front / Rear / O/S / N/S / U/C / Rooftop or

Fire Case

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action / Instruction

Total Loss, Not economical to repair vehicle caught fire.

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / L.B.A. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

\$ + RS. \$ _____

Photos _____

Others _____

TOTAL _____

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

843H

Vehicle Details

Vehicle No.:

SNA5424G

Vehicle to be Exported:

No

Intended Deregistration Date:

01 Mar 2023

Vehicle Make:

B.M.W.

Vehicle Model:

216D ACTIVE TOURER D/AB LED

Primary Colour:

Blue

Manufacturing Year:

2017

Engine No.:

34839866B37C15A

Chassis No.:

WBA2B320X0V925743

Maximum Power Output:

85.0 kW (113 bhp)

Open Market Value:

\$27,803.00

Original Registration Date:

28 Feb 2017

First Registration Date:

28 Feb 2017

Transfer Count:

1

Actual ARF Paid:

\$20,925.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

27 Feb 2027

PARF Rebate Amount:

\$13,601.00

Intended COE Rebate Details

COE Expiry Date:

27 Feb 2027

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$48,401.00

COE Rebate Amount:

\$19,331.00

Total Rebate Amount:

\$32,932.00

The information contained herein is correct as at 01 Mar 2023

OK