



Your Ref: S2M04CPD

Date: 23rd Mar 2023

Our Ref: CS3/ASM22010195/Rvy3e2-1

M/s HSBC Life (Singapore) Pte Ltd

10 Marina Boulevard

#48-01 Marina Bay Financial Centre Tower 2

Singapore 018983

(The Motor Claims Department)

Attn: Oh Vale

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GX 5129X

INSURED VEHICLE: SHD 7218C

ACCIDENT DATE: 11/10/2022

We thank you for your instruction on 22/02/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GX 5129X from M/s Automax Survey.
- b) Singapore Accident Statement of Vehicles GX 5129X and SHD 7218C.
- c) Police Report of Vehicles GX 5129X.
- d) Final Repair Bill of GX 5129X from M/s Eng Soon Painting Services.
- e) Colour damaged vehicle photographs of GX 5129X.

Pre-Repair Inspection Date: 20/10/2022 at M/s Eng Soon Painting Services, Blk 4 Yew Tee Ind Est 393 – J Woodlands Road, Singapore 677969.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

| | |
|----------------------|----------------------|
| Registration Number | : GX 5129X |
| Make & Model | : Nissan P/up Lowbed |
| Year of Registration | : 2004 |
| Chassis Number | : JN1AHGD22Z0033242 |
| Engine Capacity | : 2664 cc |

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.