

ST0S232S0003-02 / Tan Chong Motor Sales Pte Ltd[589622]
ENTRY DATE & TIME: 28/02/2023 16:29 (SGT)
SUBMITTED BY: Lawrence Teo
VERSION: 3 (01/03/2023 11:44 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	28/02/2023 16:29 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	28/02/2023 13:50 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	JURONG WEST AVE 1
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKV882A
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	TAN YING XIAN
NRIC No	SXXXX101I
Email Address	yxtan@tt.sg
Mobile Phone No	(Phone) +65-90230728
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Nissan
Model	Qashqai
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1200

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number	2100423646

DRIVER

Name of Driver	TAN YING XIAN
NRIC No	SXXXX101I
Date Of Birth	26/09/1989
Occupation	Indoor

Date Of Driving Pass	25/02/2014
Driving experience	9 YEARS
Gender	Female
Mobile Number	(Phone) +65-90230728
Alt. Phone Number	-
Email Address	ystan@tt.sg
Address	11 JURONG LAKE LINK #16-43
Address complement	-
Postcode	648155
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Change/cross lane
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

SEE ATTACHED

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SBS3388M
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Bus
Name of Driver	KONG SIEN TAT
Contact Number	-

Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

1. Location of the accident

2. Description of the accident (date, time, location, weather, etc.)

3. Description of the vehicles involved

4. Description of the driver(s) involved

5. Description of the witnesses

6. Description of the damage to the vehicles and property

7. Description of the injuries

8. Description of the investigation

9. Description of the findings

10. Description of the conclusions

11. Description of the recommendations

12. Description of the summary

13. Description of the appendix

14. Description of the references


15. Description of the contact information

16. Description of the signature

17. Description of the date

18. Description of the page number

Sketch Plan



SKETCH PLAN #2

Date: 08.22.23
 Time: 01:50
 Location: Tunong West Ave 1

driving straight but the bus cut into my
 lane and the back of the bus rub against
 my front wheel, right bumper area.
 (please see attached video.)

OTHER VEHICLE INVOLVE DETAILS

Veh No	Model	Color	Driver Name

Other Vehicle Details


 Driver 1


 Driver 2