

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/190R GS1 Reg. No. 19-900/190-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	Re	ef:	CS/AGI23002235/Kvy3m4	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Da	ate:	20/06/2023	
			Co	ode:	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMZ 4971E	Veh. Inspected		GBM 2270G	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10020804/JL	Excess (\$)		0.00	
	Assign From	FRAULEINE KHOO	Assign Date		01/03/2023	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA N VAN (A)	c.c		658	
	Engine No.	HIDDEN	Year of Reg.		2023	
	Chassis No.	JJ16003273	Colour		GREY	
	Odometer	2313 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	145/80R12	BRIDGESTONE		9 mm	
	L/H Front Tyre	145/80R12	BRIDGESTONE		9 mm	
	R/H Rear Tyre	145/80R12	BRIDGESTONE		9 mm	
	L/H Rear Tyre	145/80R12	BRIDGESTONE		9 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
	Accident Date	28/02/2023	Inspection Date		07/03/2023	
	Survey held at 60 JALAN LAM HUAT #04-53 CARROS CENTRE					
	Repairer	rer WIN AUTOMOTIVE SERVICES				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: