


ASS. R-VDY. Typist

REF: CS/FC12300 22.38/T293

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____



(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 472k.
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 3 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: Lawrence Vehicle: IN / OUT

Veh No: SLK 5265L Yr Regn: 2017 Dec.
Type: M / Car / M / Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Nissan dashikai C.C. 1197
Colour: white A/C: Insured / Std / NI / NA
Sp. Reading: 91633 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: STN FEA J1142159493
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: NIL / S/Rim / STD A/Rim or
Tyre Size: F: 225/45R19
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 2/3/23
Survey held at Tan Ching But Timber
Des. of Damages Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S Frt
The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time	Action/Instruction
13/04/23@1.43pm	finalised with LAWRENCE TEO final fig \$3636.60, 3 days.
	(Red \$665, 15%)

Date/Time, File Pass to? ☐ : Preli. Report
1) 13/04 Typist ☐ : Final Report
Date/Time, File Return to?
2) _____

Days Of Repair: 3
Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:	
Transportation:	
\$ + RS. \$	
Photos	
Others	
TOTAL	

Rep. Format: TP
Lump Sum / L.B. (\$) 3636.60

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0062/2023
DATE : 01-MAR-2023

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 65073848
FAX :
ATTN:MOTOR CLAIM DEPT

OWNER'S NAME : MR CHUA HAN XIANG , JOEL
ADDRESS : BLK 345 UPPER BUKIT TIMAH ROAD
#07-12
S(588197)
TELEPHONE NO : 93851465

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-GBK106Y
VEHICLE NO : SLV5265L
MODEL CODE : FRLARDWJ11USA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2 MY2017
ENGINE NO : HRA2551139A
CHASSIS NO : SJNFEAJ11U2159493
MILEAGE : 1 KM
DATE IN : 01/03/2023
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 23/02/2023

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR IN WORKSHOP / CAR NOT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : lawrenceteo@tanchong.com

H / P : 94568832 FAX : 64697472



2pm
APR
02/03/2023

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLV5265L

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	✓
2	ZZ/001	REPAIR AND RENEW RH FRONT DOOR AND FENDER	1000.00	✓
3	ZZ/002	S/PAINT RH FRONT FENDER AND DOOR	750.00	✓
4	ZZ/003	TRANSFER RH WING MIRROR WIRING TO NEW DOOR	120.00	✓
5	ZZ/004	TRANSFER RH FRONT DOOR MECHANICAL PARTS TO NEW DOOR	80.00	✓
TOTAL LABOUR CHARGES			2050.00	

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLV5265L

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 FENDER-OVER, FRONT RH ARC	63810-4EA0A	584.20	int ✓	
2 CANOE RIVET RH FRONT FENDER \$7.70 EA X 05	76882-0M000	38.50	net ✓	
3 CLIP FENDER \$1.50 EA X 13	01553-09321	19.50	net ✓	
4 FENDER-FRONT RH	F3100-4EAMB	738.90	bt ✓	
5 MOULDING DOOR RH FRONT	80282-4EA1B	115.20	int ✓	
6 TAPE-FR DOOR, RH	80812-4EA0A	35.00	net ✓	
7 DOOR-FRONT RH	H0100-HV0MA	1258.20	bt ✓	
8 SUNDRIES	NPN			20.00 ✓
SUB TOTAL		2789.50	0.00	20.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		557.90	0.00	0.00
GRAND TOTAL		2231.60	0.00	20.00
OVERALL TOTAL		2251.60		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLV5265L

TOTAL LABOUR CHARGES	2050.00
TOTAL SPARE PARTS CHARGES	2251.60
GRAND TOTAL	4301.60 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

Tanji 97495749
- up, 1/3/23 R220/pn
03 day,
P/R Repair before paint
Tanji @ Khantawu.

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

KKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item: it must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

ST0S232S0001 / Tan Chong Motor Sales Pte Ltd[589622]
ENTRY DATE & TIME: 28/02/2023 09:08 (SGT)
SUBMITTED BY: Lawrence Teo
VERSION: 1 (28/02/2023 09:08 (SGT))

Your NCD will be affected due to late reporting

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	28/02/2023 09:08 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	23/02/2023 17:00 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	320 MANDAI ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLV5265L
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	CHUA HAN XIANG , JOEL
NRIC No	SXXXX154J
Email Address	jconnect.joel@gmail.com
Mobile Phone No	(Phone) +65-93851465
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Nissan
Model	Qashqai
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1200

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number	1700094910

DRIVER

Name of Driver	CHUA HAN XIANG , JOEL
NRIC No	SXXXX154J
Date Of Birth	20/08/1985
Occupation	Indoor

Date Of Driving Pass	26/04/2004
Driving experience	18 YEARS AND 10 MONTHS
Gender	Male
Mobile Number	(Phone) +65-93851465
Alt. Phone Number	-
Email Address	jconnect.joel@gmail.com
Address	345 UPPER BUKIT TIMAH ROAD #07.12
Address complement	-
Postcode	588197
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit and run / Vandalism / Damaged whilst parked
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	0
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Bukit Timah Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18004629999
Alt. Police Station Phone No	(Fax) +65-64628933
Police Station Address	1 Duke Road Singapore 268914
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

SEE ATTACHED POLICE REPORT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBK106Y
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-

Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

SKETCH PLAN #2

SKETCH PLAN #3

Joel Chua (HR/HRBP Trains/Plans&Train/Plans DA)

From: Mr. Michael Eng, Esq. (Tel: 55030) Safety
Sent: 27 February 2022 11:16:10
To: joel.chua@HRBP Trains/Plans&Train/Plans DA
Cc: jerry.jimenez@Mattress Tel: Tel: M&E
Subject: Incident on East Coast Line at SMRT Mandai Depot

To: William (William) Eng

My team investigated the alleged accident and confirmed that the incident had occurred on 24 Feb 2022 at approximately 8:25pm at SMRT East Coast Line Mandai Depot staff car park B.


For your knowledge, please find attached file.

Thanks & Regards,

Michael Eng
Branch Manager
Safety, Security & Quality Office
SMRT Trains, East Coast Line

Sent from Outlook for Android

SKETCH PLAN #4



POLICE REPORT



SINGAPORE
POLICE FORCE

POLICE REPORT (WP255)

Police Station of Origin
Substation: 1070
1 Duxley Road Singapore Police Station
Tel No.: 9040 6000



REPORT NO. P. 20230207000000000000

Date Time Report Made

28/02/2023 07:05

Video Report No.

Station District No.

8

Name Of Informant

CHUA HAN JIAN (JUL)

Address

44 UPPER BUEN LIAH ROAD SINGAPORE

650197

Contact No

Home/Office

Mobile

9385 1765

Nationality

SINGAPORE CITIZEN

Email Address

JCONNECTJOE@GMAIL.COM

Occupation

HR MANAGER

Sex

Age

Date of Birth

Race

Male

37

20/08/1985

Chinese

Institution/School Name

Language

English

Date/Time Of Incident

28/02/2023 15:45

Location Of Incident

320 MANDAL ROAD TRAM DEPOT SINGAPORE

779405

STAFF CARPARK B

Brief details

I am a staff for SMRT working at SMRT Thomson East Coast Line Mandai Depot.

On 28 February 2023 at about 5pm, I went to retrieve my vehicle bearing SLV5265L which was parked at my workplace located at SMRT Thomson East Coast Line Mandai Depot Staff Carpark B. I then discovered dents and scratches on the driver side door and the front wheel area. I then contacted the

Signature Of Officer Recording The Report

E-SGT 3 TEO WH JIAN

Signature Of Informant

Signature Of Interpreter

Not applicable

Date/Time

28-02-2023 07:05

Officer in Charge Of Case

E-Tanpin Police Division Investigator Brian
INSF 111 AL JIA JIAN (JULIA)
Contact No: 83514755

Classification Of Case





SINGAPORE
POLICE FORCE

POLICE REPORT (NP299)

CONTINUATION OF REPORT



2 of 2

Report No: E-20230228/2006

security officer, namely Michael Eng and he viewed the CCTV footage and he informed me that at 12:43pm, when my vehicle first entered the depot, my car did not have any damages.

I did not lodge any report till today as SMRT was pending their investigation.

On 27/02/2023, SMRT then responded to me that another vehicle, belonging to SMRT Organization bearing GBK106Y, collided to my car at 3:45pm. However, SMRT couldn't provide me the footage and particulars of the driver due to PDPA reason and informed me to lodge a police report and made a claim against GBK106Y.

I then tried to make an insurance claim, however they require a police report. I do not wish to pursue the matter and the report is just mainly for insurance claims.

Signature Of Officer Recording The Report
E: SGT 3 TEO WEI JIAN

Signature Of Informant

Signature Of Interpreter
Not applicable

Date/Time
28/02/2023 07:36

Officer in Charge Of Case:
E: Tangle Police Division Investigation Branch
NSP-1: AL JAI IANG ALFIAN
Contact No: +65 4265

Classification Of Case