

(S/N) 501 REF:
 ASS. REC. BY: CSA **ASSIGNMENT**
 From: Date:
 Estimated Cost:
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No:
 at Workshop m/s
 of
 Insured: TMF
 Policy No.
 Claim No.
 Sum Insured: Excess:
 (Client's Record)
 Make of Vch:

Vch No: Sh 8248H Yr Reg: 15/08/18
 Type: MCar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Hyundai Ioniq cc 1580
 Colour: Blue AG: Insured / Std / N/A
 Sp. Reading: 507817 T/Radio: Insured / Std / N/A
 Eng No:
 C/Nr: Kmhccclm106426
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brakes: In order / Jammed / Leaked / Burnt or
 Mod: N/A / S/Rim / STD A/Rim or
 Tyre Size: F: 195/65R15
 R:

(Policy Condition)
 Remark: The vch had commenced its
 repair at the time of inspection.
 Bal. or Market Value:
 IDAC Accident Report: Consistent? Yes or No
 GIA / PR Sect: Consistent? Yes or No
 Est. Repairs: 2 days Res: Yes or No
 Lura Sum: 20 % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: Person Contacted:
 Vehicle: IN / OUT

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PRI / SUNI /
 TOYO / YOKO or
 Front: 5 mm R/Bal. 6 mm
 L/Bal. 5 mm U/Bal. 6 mm
 D.O.A. 28/2/23 D.O.I. 2/3/23 3342
 Survey held at Comfort
 Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Pre II. Report
 1) ☐ : Final Report
 Date/Time, File Return to?
 2)
 Report Format:
 Lump Sum / L.B.J: (\$)

Days Of Repair:
 Resurvey No. of Trip:
 Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:
 Transportation:
 S + R:
 Photos:
 Others:
 TOTAL:

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5887872

JC NO: 305547060

STOMER

COMFORT TRANSPORTATION PTE LTD
/MS 7010045
STOMER NO. 383 SIN MING DRIVE
DRESS Singapore SINGAPORE 575717
65508755 (O)

(R)
(P)

COUNT CARD NO.

REGN NO: SH 8248H

MILEAGE

MAKE: HYUNDAI

FUEL

E.....1/2.....F

MODEL: IONIQ(G2)

DATE/TIME IN: 01.03.2023 14:30

YR OF MANU: 15.08.2018

TARGET DATE

CHASSIS CODE: KMH051CVKU106496

COMPLETION DATE/TIME:

JOB DESCRIPTION

Ident Date: 28.02.2023

URE: 3P 28.02.2023


NO

LABOR CODE

DESCRIPTION

FRONT

TAKE PHOTOGRAPH
BEFORE / AFTER
SPRAY PAINTING



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

wedgement Slip

Exit Pass

No.: SH 8248H

CHIANG

Vehicle No.: SH 8248H

of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Mar 2023)
Parts: 143 HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue: Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
SH8248H/02/03/2023 11:22

23, 11:22 AM

Repairer Estimates

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)
59 Loyang Drive
Singapore 508969
Tel: 6214 8300

LKE

TP INSURER: Toklo Marine Insurance Singapore Ltd (HQ)
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	28/02/2023
Vehicle Reg. No.:	SH8248H	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Vehicle Reg. Date:	15/08/2018
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEJU076115	Chassis No:	KMHC851CVKU106496
Odometer:	507817 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	1,641.92
Miscellaneous Items	11.00
Labour	1,020.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,672.92
+ GST 8.00% (S\$)	213.83
Nett Amount (S\$)	2,886.75

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System