PRS Rec. By: GQ REF: CS/GBR22010279/Gvy3

PRS

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s V Maps Motor

of

Insured: SLT 4716U

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: $17k

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: FS6180C Yr Regn: 25 Sep/2000

Type: M.Car M.Cycle Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: HONDA CB400SFYJ c.c 399

Colour Silver A/C: Insured / Std / NI / NA

Sp.Reading — T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: NC391013540

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/60-17

R: 160/60-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or TIMSUN

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	mm	L/Bal.	mm

D.O.A. 9/10/2022 D.O.I. 17-10-2022

Survey held at W/S 12:30PM

Des. of Damages : Frt / Rear / O/S N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	$2000 - $3000
20/10/22	Submit PRS

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2) 20/10/22-typist

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 2

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation: S + RS. SI

Photos

Other:

TOTAL

Report Format:

Lump Sum / LPO: