

R —

~~The~~ ~~as~~ ~~to~~

At this ~~moment~~ moment, Survey is unable  
to confirm whether <sup>the</sup> the engine is  
damage or not. Further checks  
and some dismantling work is required.

Based on current observations, ~~the on~~ ~~damage~~  
on the damage to the air filter and carpet upholstery  
amongst others others, it would take about 4-5  
days of repair. repair.