



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI23002264/Kvy3e2 Date: 14/03/2023	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKD 3017G	Veh. Inspected	SMP 4339J	
Policy No.	P10469458R02	Coverage (\$)	0.00	
Claim No.	C10020773 /JY	Excess (\$)	0.00	
Assign From	FRAULEINE KHOO	Assign Date	02/03/2023	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA C-HR (A)	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	ZYX102180023	Colour	METALLIC YELLOW	
Odometer	170243 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/50Z R18	GREENTRAC	8 mm	
L/H Front Tyre	235/50Z R18	GREENTRAC	8 mm	
R/H Rear Tyre	235/50Z R18	GREENTRAC	9 mm	
L/H Rear Tyre	235/50Z R18	GREENTRAC	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/02/2023	Inspection Date	02/03/2023	
Survey held at	OPTIMA WERKZ PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #01-05 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		