Serveyor:	REF: CS1/LIP23	3002267/Uqy3	Special Instruction:
From (Person): ESTHER CHEAH Estimated Cost:	_ASSIGN] ofLIPDa _Bill to:	ate/Time: 01/03/2023	LS: \$ 7250 / 6 DAYS  Third Parties: Claimant:
To Inspect Vehicle No:  at Workshop m/s PRECISE AU  of NO.1 KAKI BUKIT AVE 6 #02-	JUQ 1005 TO SERVICE 34/36 SINGAPORE 417883		
Policy No:  Sum Insured:  Make of Veh: (Client's Record)		Excess:	
Date/Time: Person Contacted: Vehicle IN / OUT  Date/Time: Confirmed with Final Fig , days (Red \$ /%; Original days)  Date/Time: 14/03/23 Submit Final Fig LS \$5500 , 5 days (Red \$ 1750 / 24 %; Original 6 days)  Date/Time   Action/Instruction			
Para(1): Parts found no			
Para(1): Parts found not replaced (To highlight R or UB, LR, Etc)  Para(2): Comments on consistency of damages (Parts Not Consistent: NC)			
Para(3): Nett Value	consistency of damag	ges (Parts Not Consiste	nt: NC)
Tara(3). Nett value		T	
Salvage Value Nett Value	:RM44,000 :	Inspected/ Evaluated by:	Fee Charged: Date:  Basic & Add  Transport  Photos  Others  Total
2) 5	ile Pass to Typist	2) Date/Time	File Return to
E   D   100:	ile Pass to	4) Date/Time	File Return to
5) Date/TimeF	ile Pass to	6) Date/Time	File Return to