


Job No. _____
Date _____
P/W/S / TP RES / OD RES / EVA / INV / INV
Vehicle No. _____
Excess: _____

Veh No. JHMK 5830EX / Regd: 181 18
Type: Car / M/Cycle / Bus / Van / Lorry / Taxi / Private Motor / Truck / Trailer or
Make: Honda / Year: 2008 / CC: 1800
Colour: Black / AB: Insured / Sid / III / HA
Sp. Reading: 250779 / T/Radio: Insured / Sid / III / HA
Eng No: _____
C/No: JHMK 5830EX 2008
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Oper / Jammed / Leaked / Burnt or
Brake: Oper / Jammed / Leaked / Burnt or
Mod: Nil / S/Rim / STD/Rim or
Tyre Size: F: _____ R: _____



BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / BUMI /
TOYO / YOKO or ling long
Front: R/Bal: 8 mm L/Bal: 8 mm
Rear: R/Bal: 8 mm L/Bal: 8 mm
D.O.A: 28/2/23 D.O.I: 2/3/2023

Condition: _____
The veh had commenced its
journey at the time of inspection.
Inspected by: 27K
Report: _____ Consistent?: Yes or No
Inspected by: _____ Consistent?: Yes or No
06 days Res.: Yes or No
20 % S Val.: Yes or No
REP. / 24 HRS
Person Contacted: _____
Vehicle: IN / OUT

Survey held at _____
Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooflap or
The UIC / Chassis frame / Body Structure affected due to collision.

Action / Instruction _____

Prel. Report
 Final Report

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech Invs (\$)
 Weekend (\$)

Survey Fee
Transportation: _____
S - RS - SI
