

A.S. P.C. BY:

REF:

CS/CTI 23002307/DVP³

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SNE 5696S

Policy No. _____

Claims No. SNM23D201252/C02/CHNGPW

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remarks: The veh had commenced its repair at the time of inspection.



Bel. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repair: 3 days Res.: Yes or No

Lum Sum: 71P % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNA 9480S Yr Regr: July, 2021

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Shuttle C.C. 1496

Colour: Black A/C: Insured / Str / NI / NA

Sp. Reading: 152644 T/Radio: Insured / Str / NI / NA

Eng/No: LE B7 604838

C/No: GP 72203941

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LZA / MEC / OHTSU / PIR / SUMI /

TOYO / YOKO or Yokohama

Front Rear

R/Bal: S mm R/Bal: S mm

L/Bal: S mm L/Bal: S mm

D.O.A. 14/02/2023 D.O.L. 03/03/2023

Survey held at Vins Motor Sin Mnd

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Chinc Taping SNE 5696S

27/07/23 Insured 71P 2,554.00 with 3 days of rep (red 1049.89, 29%)

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS \$

Photos

Others

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Inve (\$)

Report Format: Merimen

I series Form 1 & 2 to 12 \$2554.00

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	202D
Vehicle Details	
Vehicle No.:	SNA94805
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Feb 2023
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE HYBRID 1.5 AUTO
Primary Colour:	Black
Manufacturing Year:	2021
Engine No.:	LEB7604838
Chassis No.:	GP72203941
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$22,491.00
Original Registration Date:	26 Jul 2021
First Registration Date:	26 Jul 2021
Transfer Count:	0
Actual ARF Paid:	\$8,488.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Jul 2031
PARF Rebate Amount:	\$6,366.00
Intended COE Rebate Details	
COE Expiry Date:	25 Jul 2031
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$59,501.00
COE Rebate Amount:	\$50,096.00
Total Rebate Amount:	\$56,462.00

The information contained herein is correct as at 21 Feb 2023

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	15/02/2023 17:25 (SGT)
Reported by	Driver
Date of Accident	14/02/2023 18:45 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	ALONG CHIN SWEE TUNNEL
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SNA9480S
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	GC Cars Leasing Pte Ltd
Company Reg No	2XXXXX202D
Email Address	lydiaang@gcgroup.com.sg
Mobile Phone No	(Phone) +65-97422693
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Honda
Model	SHUTTLE HYBRID 1.5 AUTO
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1496

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	DMHCSNA00012762200

DRIVER

Name of Driver	WENDY TENG SUQIN
NRIC No	SXXXX750F
Date Of Birth	17/04/1958
Occupation	Outdoor

Date Of Driving Pass	25/11/1981
Driving experience	41 YEARS AND 3 MONTHS
Gender	Female
Mobile Number	(Phone) +65-91075313
Alt. Phone Number	-
Email Address	TENGWENDY@HOTMAIL.COM
Address	APT BLK 712 HOUGANG AVENUE 2 #10-269
Address complement	-
Postcode	530712
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	4
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	GRAB PASSENGER
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SNE5696S
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-

Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	(Phone) +65-98561501
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLR5579C
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	ZEHRA
Contact Number	(Phone) +65-90766904
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SJP1754Z
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	DARREN
Contact Number	(Phone) +65-90939530
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by GIA Records Management Centre Personnel



A : SNA9480S
B : SNE5696S
C : SLR5579C
D : 3JP1754Z

Describe Circumstances of the Accident

On 14 Feb 2023 at 18.45 hrs, I was slowing down my vehicle (SNA9480S) to a stop along Chin Swee Tunnel. Suddenly, I felt an impact from the rear, then I realised a Vehicle B (SNE5696S) had hit onto the rear portion of my vehicle. When I came out of my vehicle to check the damages, I realised there are 4 vehicles involved in this chain collision.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

[Handwritten Signature]

Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : China Taiping Insurance
(Singapore) Pte Ltd
3 Anson Road
#15-00 Springleaf Tower
Singapore 079909

Claim Details

Case Ref. No. : TP/022023/6008
Date : 21-02-2023
Accident Date : 14-02-2023

Vehicle Details

Make & Model : Honda SHUTTLE HYBRID 1.5
AUTO
Chassis No : GP72203941
Registration No : SNA9480S

Third Party Vehicle Details

Registration No : SNE5696S

S/N	Description	Ref No.	Qty	Amount (\$S)	
1	TAILGATE <i>Paint</i>	2931	1.00	\$750.00	✓
2	TAILGATE "HONDA" EMBLEM <i>Hec</i>	1000	1.00	\$20.00	✓
3	TAILGATE "SHUTTLE" EMBLEM <i>Hec</i>	1001	1.00	\$40.00	✓
4	TAILGATE "HYBRID" EMBLEM <i>Hec</i>	1002	1.00	\$40.00	✓
5	TAILGATE RH REFLECTOR <i>Hec</i>	3194	1.00	\$260.00	X
6	TAILGATE GLASS MOULDING <i>Hec</i>	1003	1.00	\$70.00	✓
7	REAR BUMPER <i>distone</i>	2583	1.00	\$600.00	✓
8	REAR BUMPER TOWING COVER <i>Hec</i>	1005	1.00	\$20.00	X
9	REAR BUMPER RH SIDE RETAINER <i>Hec</i>	2620	1.00	\$20.00	X
10	REAR BUMPER CLIPS <i>Hec</i>	1006	10.00	\$20.00	✓
				\$1,840.00	
				\$184.00	
				\$2,024.00	
11	REAR BUMPER PARKING SENSOR <i>Hec</i>	1004	1.00	\$380.00	X
12	WINDSCREEN GUM <i>Hec</i>	1007	1.00	\$80.00	40/-
13	TO REMOVE AND REFIX TAILGATE GLASS	1008	1.00	\$180.00	120/-
14	TO REPAIR DAMAGES		1.00	\$324.00	300/-
15	TO SPRAY PAINTING		1.00	\$615.89	400/-

1540.00

add 10% 1694.00

Margin: 10%

Subtotal w/o GST:

\$3,603.89

03/03/2023 @ 1030m

Not Audited

3 days

3 days

3 days

Issued by Iswan

This is a computer-generated document. No signature is required.

Signature

3/P 2,554.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: