

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internationale Des Experts En Automobile					
A	UTOMOTIVE ENG	GRG. & MGT. DIVISION (TP)	Re	ef:	CS3/SPF22012407/Dvy3e2-1		
F	ORCE) POLICE LO	S SECTION (SPORE POLICE OGISTICS BASE (PLB) 1 INGAPORE 438675	Da	ate:	07/03/2023		
A ⁻	TTN: HAFIZUL FA	RHAN	Co	ode:	SPF		
1. Policy Particulars :- THIRD PARTY CLAIM							
In	nsured Veh.	QX 1209G	Veh. Inspected		SLQ 3540G		
Р	olicy No.		Coverage (\$)		0.00		
С	laim No.	ACS/105/009/2022/110	Excess (\$)		0.00		
А	ssign From	HAFIZUL FARHAN	Assign Date		03/03/2023		
2. Vehicle Particulars & Condition							
M	lake & Model	HONDA VEZEL HYBRID	c.c		1496		
E	ngine No.	HIDDEN	Year of Reg.		2017		
С	hassis No.	RU31249576	Colour		WHITE		
О	dometer	85079 KM	Steering		IN ORDER		
В	rakes	IN ORDER	Modification		STANDARD ALLOY RIM		
G	eneral	FAIR					
3. Conditions of Tyres							
		Size	Make		Balance		
R	/H Front Tyre	225/45 R18	BRIDGESTONE		6 mm		
L	/H Front Tyre	225/45 R18	BRIDGESTONE		6 mm		
R	/H Rear Tyre	225/45 R18	NEXEN		5 mm		
L	/H Rear Tyre	225/45 R18	NEXEN		5 mm		
4.	Description of Damages						
TI	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.						
D.	DAMAGES SEE DETAILS.						
5.	General Information						
Α	ccident Date	11/12/2022	Inspection Date		13/12/2022		
S	urvey held at	TEAM AUTOPRO PTE LTD					
		160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722					
5a.	Remarks						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						
5b.	Estimate Days of Repair						
E:	STIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days						