

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	31/12/2022 17:14 (SGT)
Reported by	Driver
Date of Accident	31/12/2022 12:20 (SGT)
Exact Location of Accident	Pioneer Rd North, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH6673B
-----------------------------------	---------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Company Reg No	1XXXXX821R
Email Address	fleetsafety@cdgtaxi.com.sg
Mobile Phone No	(Phone) +65-96286264
Alternative Phone No	(Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	I40
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1685

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Policy Number / Cover Note Number	VFX/P2419138

DRIVER

Name of Driver	VADIVER THANAPAL
NRIC No	SXXXX995J
Date Of Birth	13/05/1959
Occupation	Outdoor

Date Of Driving Pass	03/01/1984
Driving experience	38 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96286264
Alt. Phone Number	-
Email Address	fleetsafety@cdgtaxi.com.sg
Address	BLK 757 JURONG WEST STREET 74.#06-76
Address complement	-
Postcode	640757
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit and run / Vandalism / Damaged whilst parked
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	UNKNOWN
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

ON 31/12/2022 AT ABOUT 12:20HRS, I WAS DRIVING VEHICLE A (SH6673B) ALONG BOON LAY WAY TOWARDS PIONEER ROAD NORTH. AS I MAKING A LEFT TURN TO PIONEER ROAD NORTH, VEHICLE B (PA7979K) WHICH WAS ON MY RIGHT SIDE, NEVER NOTICE MY VEHICLE, MAKING A SHARP LEFT TURN INTO MY LANE AND COLLIDED ONTO VEHICLE A AT FRONT RIGHT SIDE BUMPER. AFTER THE COLLISION VEHICLE B NEVER STOP AND LEFT THE SCENE. I TRIED TO CHASE THE VEHICLE BUT I CAN IDENTIFY THE VEHICLE. NOBODY WAS INJURED.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE IS NOT SUITABLE

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PA7979K
Vehicle Manufacturer	Toyota
Vehicle Model	Hiace
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Bus
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time


 Driver's Signature (If driver is not the policyholder) / Date & Time
 31/12/2022.- 14:20HRS

 FLASH ACCIDENT
 REPORTING OFFICER

FRO BALAJI



Witnessed by Reporting Centre Personnel

Sketch Plan

Describe Circumstances of the Accident

ON 31/12/2022 AT ABOUT 12:20HRS, I WAS DRIVING VEHICLE A (SH6673B) ALONG BOON LAY WAY TOWARDS PIONEER ROAD NORTH. AS I MAKING A LEFT TURN TO PIONEER ROAD NORTH, VEHICLE B (PA7979K) WHICH WAS ON MY RIGHT SIDE, NEVER NOTICE MY VEHICLE, MAKING A SHARP LEFT TURN TURN INTO MY LANE AND COLLIDED ONTO VEHICLE A AT FRONT RIGHT SIDE BUMPER. AFTER THE COLLISION VEHICLE B NEVER STOP AND LEFT THE SCENE. I TRIED TO CHASE THE VEHICLE BUT I CAN IDENTIFY THE VEHICLE. NOBODY WAS INJURED.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time 31/12/2022.- 14:20HRS

FLASH ACCIDENT
REPORTING OFFICER

FRO BALAJI



Witnessed by Reporting Centre Personnel



IMPORTANT NOTE: Please submit the completed Addendum form to the same Accident Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: SJ0G22CV0014 Vehicle Registration No: SH6673B
 Name (as shown in NRIC): Comfort Transportation Pte Ltd NRIC/FIN/Passport No: 1XXXXX821R
 (*Vehicle Driver/Vehicle Owner) (*) Please delete as appropriate
 Address: _____ Singapore ()
 Contact (Tel): _____ Mobile No.: _____
 Email Address: _____
 Date of Accident: 31/12/2022 Time of Accident: 12:20
 Place of Accident: Pioneer Rd North,
 Insurance Company: AXA Insurance Singapore Pte Ltd

(B) ADDITIONAL INFORMATION /AMENDMENTS:

I have made a report on the above-mentioned accident and would like to include additional information or make the following amendments:

UPDATE THIRD PARTY PLATE NUMBER



Policyholder / Driver's Signature
 Date: _____

Siti

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:
 Date: 04.01.2023

GIARMC Addendum Form