

ASS. REC. BY:

REF:

61P / 23 002335 / km

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

EM

of

2397

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

866k

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

GBJ 46414

Yr Regn:

09, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy / Hiace

c.c

2982

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

136924

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTFH T02

248787

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F: Triangle

195R15X8

R: Groform

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

8

mm

L/Bal.

9

mm

L/Bal.

8

mm

D.O.A.

27/2/23

D.O.I.

7/3/2023

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S, Rear wheel shocker

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

S - RS. SI

: Fines

: Others

Report Format:

Lump Sum / I.B.I. (\$

TOTAL

EM Solution Pte Ltd

160 Sin Ming Drive #03-18/19, Sin Ming Autocity

Singapore 575722

Tel: 64560226 Fax: 64584500

GST Reg. No: 201016308K

*Not withain
21 Days &
Repair After Paint
3 days*

ESTIMATE

Date : 6th March 2023

M/s **BudgetCars Pte Ltd**
65 Ubi Crescent
Singapore 408559

Veh No : **GBJ 4641Y**
Make/Model : **Toyota Hiace**
Chassis No : JTFHT02P500248787
Date of Acc : 27.02.23
TP Veh No : YQ 1259D

| S/No | Qty | Description | Unit Price | Amount |
|---------------------|-------|---|-----------------------------------|--------------------|
| Materials | | | | |
| 1 | 1 pc | Rear Tailgate | \$ <i>21</i> | 2,162.70 ✓ |
| 2 | 1 pc | Rear Tailgate Toyota Logo | \$ <i>me</i> | 65.10 ✓ |
| 3 | 1 pc | Rear Tailgate Toyota Hiace Sticker | \$ <i>me</i> | 71.10 ✓ |
| 4 | 1 pc | Rear Tailgate Inner Board | \$ <i>Pin</i> | 408.10 X |
| 5 | 1 pc | Rear Windscreen | \$ <i>shorten</i> | 1,458.50 ✓ |
| 6 | 1 pc | Rear Boot Weatherstrip | \$ <i>me</i> | 299.10 X |
| 7 | 1 pc | Rear Bumper | \$ <i>Pin</i> | 517.10 X |
| 8 | 1 pc | Rear Lamp LH | \$ <i>Pin</i> | 303.10 X |
| | | | | \$ 5,284.80 |
| | | | Less 25% | \$ 1,321.20 |
| | | | Parts Total : | \$ 3,963.60 |
| Special Nett | | | | |
| 1 | 1 set | Rear Bumper Clips | \$ <i>me</i> | 45.00 X |
| 2 | 1 set | Reverse Sensor | \$ <i>Pin</i> | 250.00 X |
| 3 | 1 pc | Windscreen Sealant | \$ <i>me</i> | 50.00 <i>401A</i> |
| 4 | 1 pc | 70 km/h Sticker | \$ <i>me</i> | 20.00 <i>151A</i> |
| | | | Special Nett : | \$ 365.00 |
| Labour | | | | |
| 1 | | To remove & rearrange electrical wirings, check lightings | \$ | 80.00 <i>151</i> |
| 2 | | To remove, instal rear windscreen. | \$ | 200.00 <i>1201</i> |
| 3 | | To remove, transfer tail gate components | \$ | 100.00 <i>601</i> |
| 4 | | To remove, repair & replace damaged bodyparts, realign bodywork and where consistent to the accident. | \$ | 600.00 <i>2001</i> |
| 5 | | Putty and respray painting on affected portions. | \$ | 600.00 <i>2001</i> |
| 6 | | To remove & renew reverse sensor | \$ <i>me</i> | 100.00 X |
| 7 | | Rust proofing on affected portions. | \$ | 80.00 <i>301</i> |
| | | | Labour Total : | \$ 1,760.00 |
| | | | Total Parts & Labour : | \$ 6,088.60 |


for E M Solution Pte Ltd

Note: Parts quoted were based on visual inspection. Should additional parts be found damaged upon dismantling, we will seek your approval before proceeding.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|---------------------------------|--|
| Date of Submission | 28/02/2023 15:41 (SGT) |
| Reported by | Driver |
| Date of Accident | 27/02/2023 18:45 (SGT) |
| Exact Location of Accident | 106 Woodlands Industrial Park E3, Singapore 757840 |
| Additional Location Information | - |
| Country/State of Loss | Singapore |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | GBJ4641Y |
| INSURED/POLICYHOLDER | |
| Is company? | Yes |
| Name Of Registered Owner | BUDGETCARS PTE. LTD. |
| Company Reg No | 2XXXXX239Z |
| Email Address | van-related@bgc.sg |
| Mobile Phone No | (Phone) +65-96259293 |
| Alternative Phone No | - |

VEHICLE PARTICULARS

| | |
|--|---------------------------|
| Manufacturer | Toyota |
| Model | Hiace |
| Variant | - |
| Exact purpose for which vehicle was being used at time of accident | Employment |
| Are you claiming under your own insurance policy for repair to your vehicle? | No - Claiming third party |
| Vehicle Category | Commercial vehicle |
| Transmission | Auto |
| CC | 2982 |

INSURANCE COMPANY

| | |
|-----------------------------------|--------------------------|
| Name of Insurance Company | Income Insurance Limited |
| Policy Number / Cover Note Number | 5109179076-03 |

DRIVER

| | |
|----------------|---------------------------------|
| Name of Driver | MUHAMMAD RIZDUAN KHAN BIN JANNI |
| NRIC No | SXXXX407H |
| Date Of Birth | 30/04/1994 |
| Occupation | Outdoor |

SKETCH PLAN

IMPORTANT NOTICE

- 1 Please report correctly the details of the accident to speed up the claims process
- 2 This Form must be completed by the Policyholder and/or the Actual Driver.
- 3 Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Traffic Police Department for investigation.
- 6 This report will be forwarded by the Insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8 Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or


(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")


(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time





Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)



Sketch Plan

| | |
|---|--|
|  | <p>Veh. A: GBJ 4641Y</p> <p>Veh. B: YG 1259D</p> |
|---|--|