



Service Request Details

Claim

S3M04K3G

Reference

CS3/HSB23002362/Wnp3 

Loss Date

3 March 2023

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

6 Mar 2023 9:27:56 AM

Request Date

6 March 2023

Due Date

6 March 2024

Services

Pre-Repair Survey

Actions

Next Step

Complete work

More ▾

Vehicle Information

Incident Vehicle Registration #
FBT8962S

Make
TPVD CFMOTO

Model
400GT

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

OH Vale

vale.oh@axa.com.sg

Additional Instructions

Messages1	Invoices	History	Documents	Assessment	Metrics	Notes
-----------	----------	---------	-----------	------------	---------	-------

TYPE



SENT

6/3/23 5:01 PM

FROM

LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT

Assignment

BODY

Dear vale, thank you for the assignment.

