

(08/11/13) wsf

ASS - REC. BY: John

REF:

CC4/MS23002374/Rpa3

926J

COT - 2028/July

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: FBC 8011Bat Workshop m/s Leonah Senof 1006, Bank of America LN 2 #01-08Insured: MS

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 8K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBC 8011B Yr Regn: 2008 / July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: 99m GT5200 c.c. 172Colour: BLACK A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: AFGLM18WX8500074Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 110/40-13R: 130/70-13BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 3 mm R/Bal. 4 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 26/01/23 D.O.I. 06/03/23Survey held at LEONAH SENDes. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

REPAIR LIMIT - 4K

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report1) _____
Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Report Format :

Lump Sum / I.B.I: (\$ _____)

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS _____ SI

Photos

Others

TOTAL

Leong Seng Motor Pte Ltd

Blk 1006 Bukit Merah Lane 2

#01-08 Singapore 159762

Tel: 62737469 Fax: 62727669

Veh No : FBC8011B

Model : SYM GTS200

S/N	Parts Description	QTY	List Price	Nett Price	Remark
1	Mirror (L) <i>SEA /</i>		\$ 145.00		
2	Front cover <i>CM /</i>		\$ 385.00		
3	Front signal lamp <i>SEA /</i>		\$ 88.00		
4	Lower cover <i>CM /</i>		\$ 280.00		
5	Inner compartment <i>CM /</i>		\$ 320.00		
6	Coolant maintance cover <i>CM / M1 /</i>		\$ 220.00		
7	Foot board <i>CM /</i>		\$ 190.00		
8	Rear foot rest <i>SEA /</i>		\$ 75.00		
9	Tail cover <i>SEA /</i>		\$ 275.00		
10	Kick starter lever ?		\$ 80.00		
11	Air filter box <i>SEA /</i>		\$ 160.00		
12	Rear fender <i>SEA /</i>		\$ 150.00		
13	Handle bar ?		\$ 220.00		
14	Handle balancer <i>SEA /</i>		\$ 50.00		
15	Brake lever <i>SEA /</i>		\$ 45.00		
16	Handle cover ?		\$ 150.00		
17	Front fender <i>SEA /</i>		\$ 180.00		
18	Fork assy <i>SEA /</i>		\$ 850.00		
19	Fork under bracket ?		\$ 320.00		
20	Steering cone & bearing ?		\$ 150.00		
21	Front wheel rim <i>repair</i>		\$ 350.00		
22	Front wheel bearing <i>R ?</i>	2	\$ 50.00		
23	Front brake disc plate <i>SEA /</i>		\$ 195.00		
24	Rear box <i>SEA /</i>			\$ 200.00	150
25	Rear box base <i>CM /</i>			\$ 80.00	50
26	Rear no plate <i>SEA /</i>			\$ 20.00	15
27	Repair alignment			\$ 350.00	250
28	Towing 2 way 1 receipt (1 way)			\$ 100.00	?
29	Labour			\$ 450.00	300
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Less 10%

\$ 4,928.00 \$ 1,200.00

\$ 492.80

\$ 4,435.20

Rasul
Hp 90010068

90010068

5 days

L/S

06/03/23 @ 1210

Ready after repair

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 926J

Vehicle Details

Vehicle No.: FBC8011B

Vehicle to be Exported: No

Intended Deregistration Date: 08 Mar 2023

Vehicle Make: SYM

Vehicle Model: GTS200

Primary Colour: Grey

Manufacturing Year: 2008

Engine No.: KB601063

Chassis No.: RFGLM18WX8S000741

Maximum Power Output: -

Open Market Value: \$2,463.00

Original Registration Date: 11 Jul 2008

First Registration Date: 11 Jul 2008

Transfer Count: 2

Actual ARF Paid: \$370.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 10 Jul 2028

COE Category: D - Motorcycle

COE Period(Years): 10

PQP Paid: \$7,073.00

COE Rebate Amount: \$3,776.00

Total Rebate Amount: \$3,776.00