Not Nothankel Resurry Bepains

AAD2303-

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No.: 62571330 CO./ GST Reg. No. 201019626G

SHC5540P

Vehicle No.: Chassis No.:

Co UEN .: Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registriation:

SHC5540P

JTDKB3FU503092252

200303878K

TOYOTA

PRIUS GEN 4

4/3/2023

SLD4536G/ Anto Gan

29/4/2021

PART

LIST

1	FENDER SUB-ASSY, FRONT RH	\$	Bu 1,236.69
1	LINER, FRONT FENDER, RH	\$	cm 255.36 -
1	EMBLEM, SIDE PANEL, RH	\$	Ma 68.88 -
1	COVER, FRONT BUMPER	\$	CM 659.40
1	SUPPORT, FRONT BUMPER SIDE, RH	\$	cm 100.49 —
1	STAY SUB-ASSY, FRONT BUMPER, RH	\$	11-1 59.85 W
1	MOULDING, FRONT BUMPER SIDE, RH	\$	cm 120.86 —
1	COVER, FRONT BUMPER HOLE, RH	\$	MIY 38.22 -
1	UNIT ASSY, HEADLAMP, RH	\$	CM 3,325.56 -
1	JAR ASSY, WINDSHIELD WASHER	\$	NU 276.15 W
1	RIM	\$	Nu 1,995.11 —
1	GRILLE, RADIATOR, LOWER NO.1	\$	№ 224.70 X
1	COVER SUB-ASSY, FRONT PILLAR, UPR RH	\$	126.74 X
1	HOOD SUB-ASSY	\$	1,243.20 X
1	INSULATOR, HOOD	\$	518.07 X
1	HINGE ASSY, HOOD, LH	\$	1 74.34 X
1	HINGE ASSY, HOOD, RH	\$	1 74.34 X
1	MOULDING ASSY, BODY ROCKER PANEL, RH	\$	624.54 A
1	PANEL SUB-ASSY, FRONT DOOR, RH	\$	N 1,641.36 X
1	HINGE ASSY, FRONT DOOR, LOWER RH	\$	★ 139.86 ★
1	HINGE ASSY, FRONT DOOR, UPPER RH	\$	X 123.06 X
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH	\$	1 243.81 X
1	HANDLE ASSY, FRONT DOOR, OUTSIDE RH	\$	In 493.40 X
1	MOTOR ASSY, POWER WINDOW REGULATOR, FRT RH	\$	1,161.83 x
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH	\$	5- 300.62 X
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH	\$	S∽ 243.81 X
1	WEATHERSTRIP, FRONT DOOR, RH	\$	1 292.32 x
1	TAPE, BLACK OUT, NO.2 FRT RH	\$	~~ 55.02 X
1	TAPE, BLACK OUT, NO.1 FRT RH	\$	~~ 16.91 X

0 7 MAR 2023

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No.: 62571330

CO./ GST Reg. No. 201019626G

SH

	GST Reg. No. 201019626G 5 540P				
1	TAPE, BLACK OUT, NO.3 FRT RH	\$	na	33.29	X
_	TOTAL	\$		5,369.81	_ `
	25%			1,342.45	
		\$		4,027.35	
					=
	SPECIAL NETT		140		1
1	FRT BUMPER CLIP	\$	14		601m
2	FENDER LINER CLIP	\$	M	65.00	
2	DOOR TRIM CLIP	\$		130.00	
1	RH ROCKER PANEL MOULDING CLIP	\$	n	65.00	
2	FRT DOOR STICKER TRANSCAB	\$		100.00	
1	WINDSCREEN MOULDING	\$		200.00	
1	WINDSCREEN INNER SPONGE SEAL	\$	in	130.00	_X
	TOTAL			625.00	
	TOTAL PARTS	\$		1,652.35	
	LABOUR				
	To rust-proofing of the affected areas.	\$		600.00	301
	Putty and spray painting of the affected portion.	\$,200.00	301
	Panel beating, knocking and straightening the necessary				
	portion, remove and renewal of parts, adjust and realign the				
	same	\$		2,000.00	400
	same	Ф		.,000.00	100
	To transfer of door fittings, attachment and perform water				
	seepage test.	\$	n	170.00	X
	To remove and refit interior fittings, trimings, garnish,				
	fittings and other, to enable repair.	\$	Na	380.00	X
	manigs and outer, to onable repair.	*		500.00	(C) (S)
	To transfer of tire, rim and on wheel balancing.	\$		170.00	201
	To check steering geometry and computer wheel alignment	\$		220.00	601
	To Transfer Of Fender Fittings, Attachments And Perform				
	Water Seepage Test.	\$	Na	170.00	X
		3.0		HARITACIONES (CONTRACTOR)	70

AAD2303-

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No.: 62571330

CO./ GST Reg. No. 201019626G

SHC5540P

AAD2303-

TOTAL	\$ 4,910.00
OVERALL TOTAL	\$ 9,562.35

21/2 vay,

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Witnout Prejudice" basis
- No illegal modification(s, is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

SA1D2336000A / Aiax Mars Pte Ltd ENTRY DATE & TIME: 06/03/2023 16:23 (SGT) SUBMITTED BY: Aizam VERSION: 1 (06/03/2023 16:23 (SGT))

© SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission

Reported by

Date of Accident

Exact Location of Accident

Additional Location Information

Country/State of Loss

06/03/2023 16:23 (SGT)

Driver

04/03/2023 11:00 (SGT)

Singapore

ALONG TAMPINES ST 81 NEAR BLK 820B BEFORE BEFORE

TAMPINES AVE 3 JUNCTION

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SHC5540P

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

Company Reg No

Email Address

Mobile Phone No

Alternative Phone No

Yes

TRANS-CAB SERVICES PTE LTD

2XXXXX878K

claims@transcab.com.sg (Phone) +65-62876666

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to

your vehicle?

Vehicle Category

Transmission

CC

Toyota Prius

Private hire

No - Claiming third party

Taxi

Auto

1798

INSURANCE COMPANY

Name of Insurance Company

Policy Number / Cover Note Number

HSBC Life (Singapore) Pte. Ltd

VFX/P2413997

DRIVER

Name of Driver


NRIC No

Date Of Birth

ANG SIAM HOCK SXXXX492G 01/03/1952

Accident report SA1D2336000A

ACCIDENT DIAGRAM



Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder) Date & Time: VERIFIED BY AJAX MARS (ARC)
REPORTING OFFICER
ANG QI HAO, VICTOR

Reporting Centre Personnel's Signature Name: NRIC/FIN No.: