

REF: 2019

ASS. REC. BY: 2019

REF:

ASSIGNMENT

From: _____ Dealer: _____
 Estimated Cost: _____
 OD / TP / VS / TP RES / OD RES / EVA / RV / RV
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 of: _____
 Insured: TMZ
 Policy No.: _____
 Claims No.: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value: _____
 IDAC Accident Report: _____ Consistent? Yes or No
 GIA / PR Sect: _____ Consistent? Yes or No
 Est. Repair: 4 days Res: Yes or No
 Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC3199E Yr Reg: 29/05/2019
 Type: M/Car / M/Cycle / Bus / Van / Lorry / T/Tr / Prime Mover /
 Truck / Trailer or
 Make: Toyota prius cc 1798
 Colour: Blue AG: Insured / Std / N / NA
 Sp. Reading: 561547 T/Reader: Insured / Std / N / NA
 Exp No: _____
 CHX: 5TDK83F1403080414
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: N / SKIN / STD / AIR / or

Tyre Size: P: 145/65R15
 R: _____
 BS / DUN / EDNOVA / GY / FS / LZA / M/C / OHTSU / PRI / SUMI /
 TOYO / YOKO or Wellsfance
 Front: _____ Rear: _____
 RUBal: 5 mm RUBal: 6 mm
 LUBal: 8 mm LUBal: 6 mm
 D.O.A: 6/3/23 D.O.L: 7/3/23 9pm
 Survey held at: Comfury
 Des. of Damages: Frt / (Rear) / O/S / N/S / U/C / Rollover or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>L/S = 4000</u>

Date/Time, File Pass to? ☐ : PreIL Report
☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / LB.L: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation

\$ + PK: \$

Photos

Others

TOTAL

Date/Time: 06.03.2023 15:01

Page : 1

Job: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 5888406

JC NO: 305547406


OWNER: COMFORT TRANSPORTATION PTE LTD OWNER NO: 7010045 ADDRESS: 383 SIN MING DRIVE Singapore SINGAPORE 575717 (P) 65508755 (O) <td> REGN NO: SHC3199E MAKE: TOYOTA MODEL: PRIUS HYBRID(G4)06.03.2023 11:00 YR OF MANU: 29.05.2019 CHASSIS CODE: JTDKB3FU903080914 </td> <td> MILEAGE: FUEL: E 1/2 F DATE/TIME IN: 06.03.2023 11:00 TARGET DATE: COMPLETION DATE/TIME: </td>	REGN NO: SHC3199E MAKE: TOYOTA MODEL: PRIUS HYBRID(G4)06.03.2023 11:00 YR OF MANU: 29.05.2019 CHASSIS CODE: JTDKB3FU903080914	MILEAGE: FUEL: E 1/2 F DATE/TIME IN: 06.03.2023 11:00 TARGET DATE: COMPLETION DATE/TIME:
--	---	--

PRINT CARD NO.

JOB DESCRIPTION

Accident Date: 06.03.2023
NATURE: 3P.06.03.23

NO LABOR CODE DESCRIPTION



KEYED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Checklist Slip

Exit Pass

Vehicle No.: SHC3199E

JUM TOKIO

Vehicle No.:

SHC3199E

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

ComfortDelGro Engineering Pte Ltd (Co. Reg. No. 199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	06/03/2023
Vehicle Reg. No.:	SHC3199E	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS HYBRID, 1.8 CVT TAXI (A)	Vehicle Reg. Date:	29/05/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	2ZR2C22066	Chassis No:	JTDKB3FU903080914
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	4,266.83
Miscellaneous Items	11.00
Labour	2,570.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	6,847.83
+ GST 8.00% (S\$)	547.83
Nett Amount (S\$)	7,395.66

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System