

08/13 wef

ASS - REC. BY: SMR

REF:

CS/SMR 23002413/RVJ3

156A

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLA 22984

at Workshop m/s AVANTAGE

of 48 JOH GUMM RD EAST HUS-131

Insured: SMR

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: SSK

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Turn Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLA 22984 Yr Regn: 2016 / FEB

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: B.M.W 2160 ACTIVE c.c. 1496

Colour: GREY A/C: Insured / Std / NI / NA

Sp. Reading: 111474 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA 2B32050V259861

Gen. Cond: Good / Fair / Poor / Burnt

Steering: in order / Jammed / Leaked / Burnt or _____

Brake: in order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 205/60R16

R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 01/03/23 D.O.I. 08/03/23

Survey held at AVANTAGE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FAT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 30K

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: _____

1) _____
Date/Time, File Return to?

: Final Report

Resurvey No. of Trip: _____

2) _____

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

Survey Fee: _____

Transportation: _____
S + RS _____ \$

Photos _____

Others _____

Report Format : _____

Lump Sum / I.B.I.: (\$ _____)

TOTAL

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 156A

Vehicle Details

Vehicle No.: 5LA2298Y

Vehicle to be Exported: No

Intended Deregistration Date: 09 Mar 2023

Vehicle Make: B.M.W.

Vehicle Model: 216D ACTIVE TOURER D/AB LED

Primary Colour: Silver

Manufacturing Year: 2015

Engine No.: 38809385B37C15A

Chassis No.: WBA2B32050V259861

Maximum Power Output: 85.0 kW (113 bhp)

Open Market Value: \$27,414.00

Original Registration Date: 25 Feb 2016

First Registration Date: 25 Feb 2016

Transfer Count: 0

Actual ARF Paid: \$20,380.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 24 Feb 2026

PARF Rebate Amount: \$12,228.00

Intended COE Rebate Details

COE Expiry Date: 24 Feb 2026

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$43,000.00

COE Rebate Amount: \$12,733.00

Total Rebate Amount: \$24,961.00

BMW 2 Series 216d Active Tourer

Overview

Insurance

Financial

Accessories

Similar

Research

Photos

Price **\$54,800**

Depreciation **\$15,470 /yr**
[View models with similar depre](#)

Reg Date 29-Jan-2016
(2yrs 10mths 19days COE left)

Mileage 85,000 km (12k /yr)

Manufactured 2015

Road Tax \$1,082 /yr

Transmission Auto

Dereg Value \$26,882 as of today (change)

Fuel Type Diesel
(Euro 5 Engine and Above)

COE \$51,301

OMV \$27,190

Engine Cap 1,496 cc

ARF \$20,066

Curb Weight 1,395 kg

Power 85.0 kW (113 bhp)

Type of Vehicle Hatchback

No. of Owners 2