

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	ICE LTD		Ref:	CS/INC23002420/Uwy3e2	
		SINGAPORE 189557		Date:	10/03/2023	
	ATTN: CHARLOTT	E CHEW		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMP 7384H	Veh. Inspected	k	SKU 4373G	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1212675-001	Excess (\$)		0.00	
	Assign From	JESS TOH	Assign Date		07/03/2023	
2. Vehicle Particulars & Condition						
	Make & Model	MITSUBISHI LANCER EX (A)	c.c		1590	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	JMYSRCY1AFU004696	Colour		BLACK	
	Odometer	113152 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	BRIDGESTONE		6 mm	
	L/H Front Tyre	205/60 R16	BRIDGESTONE		6 mm	
	R/H Rear Tyre	205/60 R16	YOKOHAMA		6 mm	
	L/H Rear Tyre	205/60 R16	YOKOHAMA		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.  DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	02/03/2023	Inspect Date /	Time	07/03/2023 ( 11:21 AM )	
	Survey held at	SPEEDWERKZ PTE LTD				
		1 KAKI BUKIT AVE 6 #01-73, AUTOBAY @KAKI BUKIT SINGAPORE 417883				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		2 Worki	ing Days	
		·				