

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI23002427/Kny3q2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date:	14/07/2023	
			Code	: AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLT 2314J	Veh. Inspected	SMX 8151P	
	Policy No.	P10261671R03	Coverage (\$)	0.00	
	Claim No.	C10020897/JL	Excess (\$)	0.00	
	Assign From	MAYBIE CHUA	Assign Date	07/03/2023	
2.	2. Vehicle Particulars & Condition				
	Make & Model	HONDA JAZZ (A)	c.c	1318	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	JHMGK3850JX217613	Colour	METALLIC YELLOW	
	Odometer	103307 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	205/45 R16	YOKOHAMA	5 mm	
	L/H Front Tyre	205/45 R16	YOKOHAMA	5 mm	
	R/H Rear Tyre	205/45 R16	YOKOHAMA	4 mm	
	L/H Rear Tyre	205/45 R16	YOKOHAMA	4 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
	DAMAGES SEE D	DAMAGES SEE DETAILS.			
5.	General Information				
	Accident Date	05/03/2023	Inspection Date	17/03/2023	
	Survey held at LAI HUAT (MENG KEE) MOTOR PTE LTD				
		160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722			
5a.		Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ECTIMATED MODIMAL DEDICOLOGO DEDAID.				

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: