

08/11/11 Wef
ASS. R EC BY: /

REF:

ASSIGNMENT

From: _____ Date: _____
Estimate Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspected Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remarks: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lump Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

N/S	O/S

Veh No: SN64988X Yr Regn: 2019, Oct.
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Toyota Noah Hybrid. c.c. 1797
Colour: White A/C: Insured / Std / NI / NA
Sp. Reading: 79094 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: ZWR800340337.
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 195/65 R15
R: 195/65 R15
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front Rear
R/Bal. 06 mm R/Bal. 06 mm
L/Bal. 06 mm L/Bal. 06 mm
D.O.A. _____ D.O.I. 07/03/23.
Survey held at JSSM
Des. of Damages: Frt / Rear / O/S N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
TP HSBC.

MV:
PV: 474K
Nett:

052D.

Date/Time, File Pass to? ☐ : Preli. Report
1) ☐ : Final Report
Date/Time, File Return to?

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee: _____
Transportation: _____
S + RS, SI
Photos
Others
TOTAL

Report Format : _____
Lump Sum / I.B.I.: (\$ _____)