

(08/11/13) wef

ASS. REC. BY: Pam

REF:

CS3/CT123002456/Rvp3

8121

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJJ 8396at Workshop m/s EMPIRE IMAGEof 4, PANDAN LWP BLK KInsured: SJZ 5884C CT1Policy No. DMPCSNA00275402203Claims No. SNM23D201717/C02/TAYHP


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

82K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJJ8396

Yr Regn:

2018 / MARType: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA WISH 1.8 CVTc.c 1798

Colour:

GREYA/C: Insured / Std / NI / NA

Sp. Reading

63730T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDG620W 70J009184Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

04/03/23

D.O.I.

13/03/23

Survey held at

EMPIRE IMAGEDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orREAR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT 48K

21/3/23

ESTIMATE RANGE OF REPAIR / NO. OF DAYS (2K-3K) / 5 days

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 21/3/23-typist

Days Of Repair: 5

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS. \$ SI

) Photos

) Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8121
Vehicle Details	
Vehicle No.:	SJJ839B
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Mar 2023
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	2ZR0A69234
Chassis No.:	JTDGG20W70J009184
Maximum Power Output:	105.0 kW (140 bhp)
Open Market Value:	\$19,955.00
Original Registration Date:	09 Mar 2018
First Registration Date:	09 Mar 2018
Transfer Count:	0
Actual ARF Paid:	\$19,955.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Mar 2028
PARF Rebate Amount:	\$13,968.00
Intended COE Rebate Details	
COE Expiry Date:	08 Mar 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$39,000.00
COE Rebate Amount:	\$19,359.00
Total Rebate Amount:	\$33,327.00

Toyota Wish 1.8A

Overview

Insurance

Financial

Accessories

Similar

Research

Photos

Price

\$84,800

Depreciation ?

\$14,740 /yr

[View models with similar depre](#)

Reg Date

16-Apr-2018

(5yrs 26days COE left)

Mileage

82,000 km (16.6k /yr)

Manufactured ?

2017

Road Tax ?

\$976 /yr

Transmission

Auto

Dereg Value ?

\$34,765 as of today ([change](#))

OMV ?

\$19,955

COE ?

\$39,000

ARF ?

\$19,955

Engine Cap

1,798 cc

Power

105.0 kW (140 bhp)

Curb Weight ?

1,355 kg

No. of Owners ?

2

Type of Vehicle

MPV