

(08/13) WAT

ASS. REC. BY: WAT

REF:

CS/EH12300 2457/RVJ3

7152

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspected Vehicle No: SBO 8508Eat Workshop m/s Wah Hongof TOA Kuan AnInsured: BH

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
	<u>(2)</u>

Bal. or Market Value: 74K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lam Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SBA 8508E Yr Regn: 2019 / 162Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MITSUBISHI ATRAGE 1.2 CVT c.c. 1193Colour: Green A/C: Insured / Std / NI / NASp. Reading: 02657 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MMBSTA13AKH002589

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/55R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 5 mmL/Bal. 5 mmD.O.A. 05/03/23

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

REAR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 5 mmL/Bal. 5 mmD.O.I. 04/04/23Wah Hong

Date / Time Action / Instruction

REPAIR LIMIT - 50K

Date/Time, File Pass to?

☐

: Prell. Report

1) _____
Date/Time, File Return to?☐

: Final Report

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. \$

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SBD8508E MITSUBISHI ATTRAGE 1.2CVT

Page No. 1-1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>		-10%		
1	Boot lid logo badge <i>acc ✓</i>		41.00	
1	Boot lid emblem "Attrage" <i>m ✓</i>		38.00	
1	Boot lid emblem "MIVEC" <i>m ✓</i>		85.00	
1	Tail lamp RH <i>X</i>		276.00	
1	Rear bumper <i>de ✓</i>		708.00	
2	Rear bumper side retainer RH/LH@ <i>1</i> *\$28 <i>RH-m ✓</i>		56.00	
1	Rear bumper lower skirt <i>cm ✓</i>		1643.00	
1	Boot lid (Repair refer to labour)		0.00	
1	End panel (Repair refer to labour)		0.00	
1	Rear fender RH (Repair refer to labour)		0.00	
			2847.00	
			-284.70	
			2562.30	
<u>SPECIAL NETT ITEMS</u>				
1	Rear bumper clips <i>m ✓</i>		35.00 <i>30</i>	
1	Rear reverse sensor <i>?</i>		200.00	<i>?</i>
1	Boot lid emblem "CC" <i>m ✓</i>		100.00 <i>30</i>	
1	Rear bumper lower skirt clips <i>m ✓</i>		35.00 <i>30</i>	
1	Rear car plate with holder <i>X</i>		35.00	<i>X</i>
Total Parts		2967.30		



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Vehicle No. SBD8508E MITSUBISHI ATTRAGE 1.2CVT

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	600.00	300
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	800.00	500
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	90.00	40 X
4	To remove and replace rear reverse sensor	100.00	40
Labour Total :		1590.00	
TOTAL (PARTS & LABOUR):		4557.30	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Panel
Hq 90010068
3 days
Hs
04/04/23 @ 1400
Reey after repair

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 715Z

Vehicle Details

Vehicle No.: SBD8508E
Vehicle to be Exported: No
Intended Deregistration Date: 05 Apr 2023
Vehicle Make: MITSUBISHI
Vehicle Model: ATTRAGE 1.2 CVT
Primary Colour: Silver
Manufacturing Year: 2019
Engine No.: 3A92UHX7366
Chassis No.: MMBSTA13AKH002589
Maximum Power Output: 59.0 kW (79 bhp)
Open Market Value: \$13,843.00
Original Registration Date: 06 Dec 2019
First Registration Date: 06 Dec 2019
Transfer Count: 0
Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 05 Dec 2029
PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 05 Dec 2029
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$30,000.00
COE Rebate Amount: \$20,000.00
Total Rebate Amount: \$23,750.00

Mercedes-Benz A-Class A200 Progressive

[Overview](#)

[Insurance](#)

[Financial](#)

[Accessories](#)

[Similar](#)

[Research](#)

[Photos](#)

Price	\$137,800		
Depreciation	\$16,990 /yr View models with similar depre	Reg Date	04-Apr-2020 (6yrs 11mths 29days COE left)
Mileage	25,000 km (8.3k /yr)	Manufactured	2019
Road Tax	\$586 /yr	Transmission	Auto
Dereg Value	\$54,846 as of today (change)	OMV	\$32,681
COE	\$37,900	ARF	\$37,754
Engine Cap	1,332 cc	Power	120.0 kW (160 bhp)
Curb Weight	1,375 kg	No. of Owners	2
Type of Vehicle	Hatchback		