

Vehicle Damage Assessment Report for [SNA7281M]

Estimate Created: 18/04/2023 03:50 by Insurlogic 5 (Insurlogic_Pte_Ltd)

Owned: 18/04/2023 07:29 by Insurlogic 5 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Skoda	Model	Scala
Engine Type			
License Plate Number	SNA7281M	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$5,082.74 WITH 3 WORKING DAYS

Insurlogic 5 (18/04/2023 07:29)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
REAR BUMPER		1	1656.46	0.00 %	1,656.46
SENSOR BRACKET		1	14.14	0.00 %	14.14
GEBERHALTER		3	14.14	0.00 %	42.42
SEAL RING SATIN BLACK		1	1.53	0.00 %	1.53
2K PLASTIC ADHESIVE		1	84.64	0.00 %	84.64
BONDING AGENT FOR PLASTIC		1	74.37	0.00 %	74.37
BUMPER SPOILER		1	260.15	0.00 %	260.15
LHR REFLECTOR		1	49.03	0.00 %	49.03

Parts Subtotal 2,182.74

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
COATING		1.0	100.00	0.00 %	100.00

Materials Subtotal 100.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
B&P CHECK SHORT CIRCUIT/HARNESS REPAIR	RnR	280.00	0.00 %	280.00
B&P DIAGNOSIS & PROGRAMMING	RnR	480.00	0.00 %	480.00
LABOUR	RnR	840.00	0.00 %	840.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
SPRAY PAINT	Full spray	1200.00	0.00 %	1,200.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 1,600.00

Paint Labor Subtotal 1,200.00

Labor Subtotal 2,800.00

Summary

Repair Cost	5,082.74
Discount(0 %)	(0.00)
	5,082.74
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	5,082.74