

ASS. REC. BY:

REF:

C72/ 23002467/K

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SKG 45876 Yr Regn: 07, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 520i

c.c

1997

Colour

M. Black

A/C: Insured / Std / NI / NA

Sp. Reading

158831

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBAXG12010D 291515

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / RIM or

Tyre Size:

F:

R:

225/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

28/2/23

D.O.I.

9/3/2023

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

FR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

## REPAIR DETAILS

### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Mar 2023)  
Parts: 143 BMW 520i 2.0 D/AB 2WD 4DR GAS/D NAV (A) (Catalogue: Merimen Singapore 1.0)  
Labour: Repairer's (Price-denominated Standard List)  
Print Code: (Unsubmitted, no print-code for SKQ4587C)  
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*

SKQ 4587C

P/china

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC FRONT BONNET	0.00	0.00	*1,900.00 F
2	1		*1 PC LH HEADLAMP	0.00	0.00	*1,700.00 F
3	1		*1 PC FRONT LH BUMPER RETAINER	0.00	0.00	*30.00 F
4	1		*1 PC FRONT LH BUMPER SENSOR	0.00	0.00	*180.00 F
5	1		*1 PC FRONT LH FENDER	0.00	0.00	*560.00 F
Sub Total (\$)						4,370.00
+ Margin on L,N Items 10.00% (\$)						437.00
Total Parts (\$)						4,807.00

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

### Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

### Estimates on Labour

No	Particulars	Lab. Type	Amount
<b>Labour Items</b>			
1	REMOVE AND REFIT FRT BUMPER, HEADLAMP, FRT LH FENDER, BONNET AND REALIGN THE SAME.	New	500.00
2	PUTTY AND RESPRAY ON BONNET, FRT LH FENDER AND FRT BUMPER.	New	700.00
Gross Labour Cost (\$)			1,200.00

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify  
the Repairer of the following:


- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

**TP INSURER:** China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

Singapore

**PARTICULARS OF CLAIM**

Claim Type: **THIRD PARTY**  
Policy No:  
Vehicle Reg. No.: **SKQ4587C**  
Party At Fault: **UNKNOWN**  
Driver (TP): **LO JOY KWOK**

Ref. No: **TP/CHINA**  
Date of Loss: **28/02/2023**  
Driveable?

Make/Model: **BMW 520I, 2.0 D/AB 2WD 4DR**  
**GAS/D NAV (A)**

Vehicle Reg. Date: **30/07/2013**Vehicle Colour: **BLACK**Engine No: **B3730484N20B20B**Chassis No: **WBAXG12010D291515**Odometer: **0 KM**

Paint Type:

Total Loss? **NO**Est. Duration of Repair  
(day) **0**

*Not Notified*  
*6/1/23*  
*Repair After Paint*  
*4 days*

Description of Accident/Loss: **REFER GIA REPORT ATTACHED**Present Location: **CHENG HOE MOTOR PTE LTD (YISHUN)****COST OF CLAIMS****Amount**

Parts	0.00
Miscellaneous Items	0.00
Labour	1,200.00
Paintwork Labour	0.00
Towing	0.00

**Gross Total (\$\$)** **1,200.00****+ GST 8.00% (\$\$)** **96.00****Nett Amount (\$\$)** **1,296.00****This claim is handled by: EFEEDA BINTE MOHAMED OTHMAN**

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	28/02/2023 18:44 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	28/02/2023 12:20 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	BLK 324 BT.BATOK OPEN CARPARK(LOT NO.10)
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SKQ4587C

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	LO JOY KWOK
NRIC No	SXXXXX041D
Email Address	combee659@gmail.com
Mobile Phone No	(Phone) +65-93742525
Alternative Phone No	-

#### VEHICLE PARTICULARS

Manufacturer	BMW
Model	520I 2.0L AT D/AB 2WD 4DR GAS/D NAV
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1997

#### INSURANCE COMPANY

Name of Insurance Company	Income Insurance Limited
Policy Number / Cover Note Number	5082473313-06

#### DRIVER


Name of Driver	LO JOY KWOK
NRIC No	SXXXXX041D
Date Of Birth	16/08/1945
Occupation	Indoor

Describe Circumstance of the Accident

NOTE PLEASE TAKE NOTE THAT YOUR INSURER HAVE 14 DAYS TIME FRAME for you to submit OWN DAMAGE Claim under your Own Comprehensive policy. Pls check your policy for more information.

( ) Claim Own Policy ( ☒ ) Claim Third party ( ) Reporting Only  
( ) Claim OD/ TP at other workshop ( )

Sketch Plan



I park my car at lot no: 10 stationary. A lorry (YQ 1763P) while reversing accidentally onto my car front left portion and cause damage. No one was injured.

Declaration

I/We declare the foregoing particulars are true in every respect.

*[Signature]*  
28/02/2023  
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

*[Signature]* 28/2/23  
Afida (W)  
Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)