

LI HONG AUTO SERVICES PTE LTD

NO.1 BUKIT BATOK CRESCENT

#03-58 WCEGA PLAZA

SINGAPORE 658064

Phone Number: 65700079 / 90276341

Fax Number:

Customer:		Date:	12/8/2022 11:31 AM
Company:		VIN	
License NO:	SLF 7009 G	Technician:	T
Odometer:		Order NO:	

VEHICLE ALIGNMENT REPORT

MAZDA, 3 1.6/2.0, 08-08 (Customized)

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	----	2°04'	4°04'	----
		Right	----	2°04'	4°04'	----
	Camber	Left	-0°18"	-1°41'	0°19'	-0°18"
		Right	-2°30'	-1°41'	0°19'	-2°30'
	Toe	Left	-0.6mm	-0.6mm	1.7mm	-0.6mm
		Right	10.2mm	-0.6mm	1.7mm	10.2mm
Rear	Camber	Left				
		Right				
	Toe	Left				
		Right				
	Thrust Angle	Total				
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left	----	----	14°02'	14°02'	----
	Right	----	----	14°02'	14°02'	----
Included Angle	Left	----	----	----	----	----
	Right	----	----	----	----	----
Toe Out On Turns	Left					
	Right					
Max Turn Inside	Left	----	----	36°48'	42°48'	----
	Right	----	----	36°48'	42°48'	----
Toe Curve Change	Left					
	Right					
Setback	Front					
	Rear					
Track Width Diff.						
Wheel Base Diff.						
Front Ride Height	Left					
	Right					
Rear Ride Height	Left					
	Right					
Frame Angle						

THANK YOU FOR YOUR SUPPORT