

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	HSBC LIFE (SINGAPORE) PTE LTD		Ref	CS3	/HSB23002492/Swy3e2	
	10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983		Dat	e: 23/0	3/2023	
	ATTN: OH VALE		Cod	e: HSB	3	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHA 9929L	Veh. Inspected	GBB	3 7563L	
	Policy No.	VFX/P2419140	Coverage (\$)	0.00		
	Claim No.	S3M04K93	Excess (\$)	0.00		
	Assign From	OH VALE	Assign Date	09/0	3/2023	
2.	Vehicle Particulars & Condition					
	Make & Model	NISSAN CABSTAR	c.c	2953	3	
	Engine No.	HIDDEN	Year of Reg.	2010	)	
	Chassis No.	JN1SC2F24Z0801366	Colour		/ER	
	Odometer	287296 KM	Steering	IN C	ORDER	
	Brakes	IN ORDER	Modification	STA	NDARD ALLOY RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make	Bala	ance	
	R/H Front Tyre	195/70 R15	YOKOHAMA	5 mr	m	
	L/H Front Tyre	195/70 R15	YOKOHAMA	5 mr	n	
	R/H Rear Tyre	155 R13	GITI	5 mr	m	
	L/H Rear Tyre	155 R13	GITI	5 mr	n	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
5.	General Information					
	Accident Date	06/03/2023	Inspect Date / Time	09/0	3/2023 ( 04:30 PM )	
	Survey held at HENG YAP SENG AUTO SERVICE					
	160 SIN MING DRIVE #08-13 SIN MING AUTOCITY SINGAPORE 575722					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$9,000-\$10,000					
5b.		Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days					

Report Ref No. CS3/HSB23002492/Swy3e2

Inspected By

S MOHAMED IRFAN BIN MOHAMED IQUBAL

K.K.LAU CPT(RET)

Asst. Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser