

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMY 3700H

at Workshop m/s BORNBO

of PONDON CRESTON

Insured: FCI

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 132K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SMY 3700H Yr Regn: 2021 1 MAR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: TOYOTA PRIUS PLUS A c.c. 1798

Colour: GREY A/C: Insured / Std / NI / NA

Sp. Reading: 200250 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTD ZS 3EU 80J 05 86 86

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / R/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 07/03/23 D.O.I. 09/03/23

Survey held at BORNBO

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

REPAIR LIMIT - 80K

Date/Time, File Pass to?

: Preli. Report

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation: \_\_\_\_\_

S + RS \_\_\_\_\_ \$

Photos

Others

Add Fee:

: Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Report Format :

Lump Sum / I.B.I.: (\$ \_\_\_\_\_)

inchcape  
 Co. Reg No. : 196700086Z  
 GST Reg No. : MR-8500000-9  
 No. 2 PANDAN CRESCENT  
 SINGAPORE 128462, Tel no.: 6631 1188

## ESTIMATE

Account Details		Account No.	Customer Details	
THIRD PARTY CLAIM		S1000020 / TPCLAIM	M/S Grab Rentals Pte Ltd	
		Document No. 0	3 Media Close #01-03/06 Singapore 138498	
		Document Date 08/03/2023	Work: 65703925	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	ZVW40R	AWXEBW Q3	02/03/2021	SMY3700H	0	20537	66TP/SMY3700H/070323

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDZS3EU80J058656	2ZR2H01604	60	Shashitharan	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:PA9987Z ACC DATE:07/03/23 DRIVE IN:07/03/23 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50 100.00
2	B	BP-LAB2 CHECK WIRING UPON COMPLETION OF REPAIR				240.00
3	B	BP-LAB2 TRANSFER RH FRT AND REAR DOOR MECHANISM				396 792.00
4	Z	BP-SLANT SUPPLY SEALANT (NETT) 2 PANEL				100 200.00
5	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00
6	B	BP-LAB2 REPL ACC AFF PARTS AND PANEL				3168.00
7	B	BP-RES2 RESRPAY ACC AFF AREA				2952 4582.00
8	1	U87915-74010 B0 COVER, OUTER MIRROR, MIS	1.00	158.10		158.10
9	2	U87910-47220 MIRROR ASSY, OUTER cut	1.00	1554.10		1554.10
10	3	U75922-47030 TAPE, BLACK OUT, m	1.00	57.70		57.70
11	4	U75985-47040 STRIPE, FR DOOR, m	1.00	36.80		36.80
12	5	U75965-47020 STRIPE, FR DOOR, m	1.00	26.30		26.30
13	6	U75975-47030 STRIPE, FR DOOR, m	1.00	18.60		18.60
14	7	U67001-47111 PANEL SUB-ASSY, FR H	1.00	1563.20		1563.20
15	8	U68710-12151 HINGE ASSY, FR DOOR, ?	1.00	117.20		117.20

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Co. Reg No. : 196700086Z  
 GST Reg No. : MR-8500000-9  
 No. 2 PANDAN CRESCENT  
 SINGAPORE 128462, Tel no.: 6631 1188

## ESTIMATE

Account Details		Account No.	Customer Details	
THIRD PARTY CLAIM		S1000020 / TPCLAIM	M/S Grab Rentals Pte Ltd	
		Document No. 0	3 Media Close #01-03/06 Singapore 138498	
		Document Date 08/03/2023	Work: 65703925	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	ZVW40R	AWXEBW Q3	02/03/2021	SMY3700H	0	20537	66TP/SMY3700H/070323

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDZS3EU80J058656	2ZR2H01604	60	Shashitharan	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
16	9	U68730-12120 HINGE ASSY, FR DOOR, ?	1.00	133.20		133.20
17	0	U69210-74030 B0 HANDLE ASSY, FR <i>scr</i>	1.00	469.10		469.10
18	1	U69217-74010 B0 COVER, FR DOOR <i>scr</i>	1.00	18.20		18.20
19	2	U69250-74010 B0 COVER ASSY, DOOR	1.00	40.40		40.40
20	3	U67003-47180 PANEL SUB-ASSY, RR <i>scr repair</i>	1.00	1556.50		1556.50
21	4	U75923-47030 TAPE, BLACK OUT, <i>X</i>	1.00	57.70		57.70
22	5	U75977-47050 STRIPE, RR DOOR, <i>X</i>	1.00	26.30		26.30
23	6	U75987-47050 STRIPE, RR DOOR, <i>X</i>	1.00	31.70		31.70
24	7	U75979-47060 STRIPE, RR DOOR, <i>X</i>	1.00	26.30		26.30
25	8	U58741-47020 PROTECTOR, QUARTER <i>m</i>	1.00	27.60		27.60

*Panel*  
*4p 2m 10v168*  
*7 days*  
*09/03/23*  
*@1520*  
*Ready before paint*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	15,209.00
Acknowledged by Repairer Signature:	Please acknowledge receipt of vehicle	Parts 5,919.00	GST 8.00%	1,216.72
Date:		Labour 9,290.00	Less	0.00
		Sublet 0.00	Amount Due	16,425.72
		Lubrication/Fluid 0.00		
		Others 0.00		

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	200G
<b>Vehicle Details</b>	
Vehicle No.:	SMY3700H
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Mar 2023
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS PLUS (AUTO)
Primary Colour:	Silver
Manufacturing Year:	2020
Engine No.:	2ZR2H01604
Chassis No.:	JTDZS3EU80J058656
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$27,507.00
Original Registration Date:	02 Mar 2021
First Registration Date:	02 Mar 2021
Transfer Count:	0
Actual ARF Paid:	\$15,510.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Mar 2031
PARF Rebate Amount:	\$11,632.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	01 Mar 2031
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,100.00
COE Rebate Amount:	\$39,914.00
<b>Total Rebate Amount:</b>	<b>\$51,546.00</b>