

ŠKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



SKODA

Commercial Vehicles

Quotation

Non binding - Preview

10/3/2023 @ 11.30am - 12.30pm.

Page

1/2

Company
ALLIANZ
INSURANCE SINGAPORE PTE. LTD.
79 ROBINSON ROAD
#09-01
SINGAPORE 068897

Customer Details:
Mr
RITESH
AJMANI
16 SIMEI STREET 1
#07-12
SINGAPORE 529942

Document no.
Document date 09-03-2023
Customer no. 5211052769
Customer GST-ID 201903913C
Dealer 30001
Job order number 2023006251/ 1
Job order date 06-03-2023
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SMZ9286S	NS73KCP4	25-05-2021	TMBKC7NS2M8049808	Kodiaq Ambition Plus 1.4 I TSI 110kW DSG	31,036

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT/HARNES REPAIR				#6	✓ 280.00 ✓	302.40
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#6	✓ 480.00 ✓	518.40
9801B001	TO ALIGN LED HEADLIGHT				#6	100.00 X	108.00
565807221	Cover For FRT BUMPER	1	pcs.	2,208.62	10.00% #6	✓ 1,987.76	2,146.78
565919493 GRU	Sensor Bracket	1	pcs.	15.25	10.00% #6	✓ 13.73	14.83
565919494 GRU	Sensor Bracket	1	pcs.	23.60	10.00% #6	✓ 21.24	22.94
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	84.64	10.00% #6	✓ 76.18	82.27
D 822150A1	Bonding Agent For Plastic	1	pcs.	74.37	10.00% #6	✓ 66.93	72.28
565807050	Guide Piec BUMPER SIDE BRACKET RH	1	pcs.	68.38	10.00% #6	61.54 X	66.46
565807061 9B9	Front Spoiler	1	pcs.	441.02	10.00% #6	✓ 396.92	428.67
565807611 9B9	End Plate BUMPER SPOILER CLOSING ELEMENT	1	pcs.	185.36	10.00% #6	166.82	180.17
565807241 9B9	Trim TOWING COVER	1	pcs.	19.35	10.00% #6	✓ 17.42	18.81
565853653A 9B9	Grille RADIATOR GRILLE	1	pcs.	424.75	10.00% #6	382.28 X	412.86
565853761 2ZZ	Cover Stri RADIATOR GRILLE CHROM	1	pcs.	472.67	10.00% #6	425.40 X	459.43
565853677E 9B9	Unbekannt BUMPER CTR LOWER GRILLE	1	pcs.	195.13	10.00% #6	✓ 175.62	189.67
565807368 9B9	Cap BUMPER LOWER GRILLE RH	1	pcs.	58.99	10.00% #6	✓ 53.09	57.34
565853666C 9B9	Trim For B RHS LOWER GRILLE (SENSOR GRILLE)	1	pcs.	28.74	10.00% #6	25.87 X	27.94
565121295D	Air Duct AIR GUIDE LOWER	1	pcs.	108.75	10.00% #6	✓ 97.88	105.71
565807109G	Reinforcem	1	pcs.	973.66	10.00% #6	✓ 876.29	946.39
565807093	Cross Memb	1	pcs.	102.89	10.00% #6	92.60 X	100.01
N 90993603	Hex Socket Head Bolt	2	pcs.	2.37	10.00% #6	4.27 X	4.61
567941016H	Unbekannt RHS H/LAMP	1	pcs.	3,075.02	10.00% #6	2,767.52 X	2,988.92
565854732 9B9	Trim For W RHS WHEEL ARCH	1	pcs.	276.56	10.00% #6	✓ 248.90	268.81
3T0853431A 2ZZ	Foil Inscr RHS FENDER NAME PLATE (L&K)	1	pcs.	86.19	10.00% #6	✓ 77.57	83.78
	LABOUR				#6	720 ✓	
	SPRAY PAINT			720.00	#6	2,160.00	2,332.80
	ALLIANZ NON IN HOUSE OD			680.00	#6	2,040.00	2,203.20
	DOA: 3/3/2023						
	EXCESS:						
	SURVEY BY:						

✓1360

ŠKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



SKODA

Commercial
Vehicles

Quotation

Non binding - Preview

Page

2/2

Company
ALLIANZ
INSURANCE SINGAPORE PTE. LTD.
79 ROBINSON ROAD
#09-01
SINGAPORE 068897

Customer Details:
Mr
RITESH
AJMANI
16 SIMEI STREET 1
#07-12
SINGAPORE 529942

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor
09-03-2023
5211052769
201903913C
30001
2023006251/ 1
06-03-2023
SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SMZ9286S	NS73KCP4	25-05-2021	TMBKC7NS2M8049808	Kodiahq Ambition Plus 1.4 I TSI 110kW DSG	31,036

Quotation valid till 13-03-2023

Tax Code	Labour	Material	Material Discount	GST %	GST	Total Discount	Total amount excl. GST	Total amount incl. GST
#6	860.00	12,235.83	892.85	8%	1,047.67	892.85	13,095.83	14,143.50
Total	860.00	12,235.83	892.85		1,047.67	892.85	13,095.83	14,143.50

Customer

Service Advisor

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rame
Hp 90010068
3 day
10/03/23 @ 1140
EXCESS: TBA
REPAIR
Resy before paint