

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBK 4566B

at Workshop m/s CYCLE & CARRIAGE

of PANORAMA GARDEN

Insured: CTI

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<u>N/S</u>	<u>O/S</u>

Bal. or Market Value: 67K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: GBK 4566B Yr Regn: 2020 / 1914

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: CITROEN BERLINGO 1.5 BLUE HDI c.c 1499

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 025518 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: VR 7EFYH ZRL 3662679

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 02/03/23 D.O.I. 10/03/23

Survey held at CYCLE & CARRIAGE (PA)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 49K

Date/Time, File Pass to?

: Preli. Report

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$ \_\_\_\_\_)



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 64792792



CITROËN

ESTIMATE

Company Reg No. 200609327M
GST Reg No. MR-8500111-X

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for KATONG HAIR-CUT & CURL SALON, vehicle registration GBK4566B, and engine details.

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Row 1: CSM00073, Cash, 04/03/2023/ 08:48, TLK, 282 / Kevin Leong, 19932

Main itemized list table with columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Includes items like 'REPLACE FRONT BUMPER PANEL', 'PAINT WORK ON FRONT BUMPER PANEL', etc. Includes handwritten 'Estimate' watermark and handwritten amounts.

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 64792792



CITROËN

ESTIMATE

Company Reg No. 200609327M
GST Reg No. MR-8500111-X

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for KATONG HAIR-CUT & CURL SALON, contact info, and vehicle registration details.

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Row 1: CSM00073, Cash, 04/03/2023/ 08:48, TLK, 282 / Kevin Leong, 19932

Main items table with columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists various car parts like bumpers, grilles, and brackets with handwritten notes and corrections.

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens, Singapore 609339 Tel: (65) 64792792



Company Reg No. 200609327M  
GST Reg No. MR-8500111-X

ESTIMATE

Invoice Name & Address

Owner Name & Vehicle Info

KATONG HAIR-CUT & CURL SALON

Cust No/Name

/ KATONG HAIR-CUT & CURL SALON

1 BROOKE ROAD  
#B1-11 KATONG PLAZA  
SINGAPORE 429979

Reg No/Reg Date

GBK4566B / 06/08/2020

Date In/Mileage

03/03/2023/ 0

Chassis No

VR7EFYHZRLJ662679

Engine No

10Q4DR0017317

Contact No Mobile: 98658268

Make/Model

CITCV/K9 BERLINGO L2 1.5 BLUEHDI 130 EAT

Colour/Trim

WPP BLANC BANQUISE / GY GREY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	04/03/2023/ 08:48	TLK	282 / Kevin Leong	19932

Description of Goods / Services

Qty

Unit Price

Disc%

Amount

M BUMPER BRACKET RH SUPERIEUR ?	1.00	171.00	0.00	171.00
M BUMPER CROSSMBR AR - ASS ?	1.00	691.00	0.00	691.00
M FIXING STUD	1.00	193.00	0.00	193.00
M SIDE DOOR LH AR	1.00	2391.00	0.00	2391.00
M SIDE DOOR RH AR	1.00	2471.00	0.00	2471.00
M DOOR HINGES	1.00	388.00	0.00	388.00
M DOOR HINGES	1.00	388.00	0.00	388.00
M WEATHERSTRIP	1.00	321.00	0.00	321.00
M DOOR SEAL	1.00	139.00	0.00	139.00
M WATER JET SEAL	1.00	103.00	0.00	103.00
M ADHESIVE KIT	1.00	39.00	0.00	39.00
M FIX PORTES	1.00	132.00	0.00	132.00
M BADGE	1.00	117.00	0.00	117.00
M BADGE	1.00	91.00	0.00	91.00
M TAIL-LIGHT RH	1.00	268.00	0.00	268.00
M TAIL-LIGHT LH	1.00	268.00	0.00	268.00
M STOP LIGHT	1.00	113.00	0.00	113.00
M LICEN PLAT LAMP	1.00	36.00	0.00	36.00

Resue

Hp 900100368

8 days

10/03/23 @1610

Estimate

Resue before paint

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

Parts	16,345.00
Labour	13,330.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	2,570.00
<b>Total (w/o GST)</b>	<b>32,245.00</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	600L
<b>Vehicle Details</b>	
Vehicle No.:	GBK4566B
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Mar 2023
Vehicle Make:	CITROEN
Vehicle Model:	BERLINGO VAN 1.5 BLUEHDI EAT8 L2
Primary Colour:	White
Manufacturing Year:	2020
Engine No.:	10Q4DR0017317
Chassis No.:	VR7EFYHZRLJ662679
Maximum Power Output:	-
Open Market Value:	\$23,762.00
Original Registration Date:	06 Aug 2020
First Registration Date:	06 Aug 2020
Transfer Count:	0
Actual ARF Paid:	\$1,189.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	05 Aug 2030
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$23,888.00
COE Rebate Amount:	\$17,671.00
<b>Total Rebate Amount:</b>	<b>\$17,671.00</b>

# Citroen Berlingo 1.5A BlueHdi

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price

**\$69,800**

Lifespan 

04-Oct-2040

Depreciation 

\$9,220 /yr

[View models with similar depre](#)

Reg Date

05-Oct-2020

(7yrs 6mths 22days COE left)

Mileage

N.A.

Manufactured 

2020

Road Tax 

N.A.

Transmission

Auto

Dereg Value 

\$21,641 as of today (change)

Fuel Type

Diesel

COE 

\$28,589

OMV 

\$24,504

Engine Cap

1,499 cc

ARF 

\$1,226

Curb Weight 

1,480 kg

No. of Owners 

1

Type of Vehicle

Van