

Service Request Details

Claim	S3M04KAX
Reference	CS/HSB23002545/Acy3e2 
Loss Date	8 March 2023
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	9 Mar 2023 12:52:41 PM
Request Date	9 June 2023
Due Date	
Services	Pre-Repair Survey

Actions

Next Step Add invoice

Add Invoice

Vehicle Information	
Incident	SGZ1313X
Vehicle	
Registration #	
Make	TPVD
Model	UNKNOWN
Service Address	
, , ,	
Primary Contact/Insured	

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Additional Instructions

Claim Handler

KHOR Saw Theng

sawtheng.khor@axa.com.sg

- Messages3
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

Invoice

Surveyor/ Assessor expense

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 HSB-LKKInvoice-AC2304157.pdf.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	30 June 2023
 LKKInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	30 June 2023

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 LKKAdjustment.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	30 June 2023
 Resurvey Photo-1.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	30 June 2023
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	30 June 2023
 Photographs.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	27 June 2023
 Resurvey Photographs.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	27 June 2023
 Immediate Advice.pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	27 June 2023
 SJ0G23380016-SHA3241B.pdf.pdf	Reports & Statement	Accident statement	STACEY Ng Pei Sze 2	9 March 2023
 EMAIL FORM SOLICITOR FOR TP	Letters and	Others	NIKAM Santosh Pandurang	9 March

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
REG.msg.msg	Correspondence			2023