

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATEDATE: 09.03.2023INSURANCE: ALLIANZ (45)MODEL: Hyundai IoniqSURVEYOR: NAVEHICLE NO.: SHD4781LMVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$ del 459.40
	Rear Bumper Reinforcement	1		\$? 394.80
	Rear Bumper Reinforcement Bracket RH	1		\$? 138.10
	Rear Bumper Side Brackets RH	1		\$ del 55.80
	Rear Bumper Centre Moulding	1		\$ del 451.25
	Rear Bumper Lower Centre Moulding	1		\$ dis 155.00
	Rear Bumper Cover Clips	10	\$ 2.20	\$ del 22.00
	Rear Bumper Side Under Cover RH	1		\$ del 108.00
	Rear Bumper Reflector Lamp RH	1		\$ del 41.45
	Rear Bumper Tow Cover	1		\$ X 98.80
	Rear Bumper FogLamp	1		\$? 201.50
	Rear Smart Key Antenna	1		\$? 40.50
	TailLamp RH	1		\$ X 935.40
	SUB TOTAL			\$ 3,102.00
	LESS 25%			\$ 775.50
	DISCOUNTED TOTAL			\$ 2,326.50
	Rear Bumper Mat	1		\$ 50.00 <i>new</i>
	Reverse Sensors	1		\$ 180.00 <i>new</i>
	Rear No.Plates With Trim Cover	1		\$ 55.00 <i>new</i>
	S/NETT TOTAL			\$ 285.00
	SPARE PARTS TOTAL			\$ 2,611.50
	Labour Charge			
	Panel Beating			\$ 400.00 <i>350</i>
	Spray Painting Charge			\$ 300.00 <i>250</i>
	Check Lightings			\$ 40.00 <i>30</i>
	Remove/Refix Reverse Sensor			\$ 120.00 <i>30</i>
	<i>Tanji M 9749 5749</i>			
	<i>wp/ 10/3/23 @ 3pm</i>			
	<i>4/5 Remedy after repair</i>			
	<i>2 days</i>			
	<i>Tanji M 9749 5749</i>			
	TOTAL LABOUR			\$ 860.00
	ESTIMATE TOTAL			\$ 3,471.50

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Acknowledged by Repairer

Signature:

Date:

am: ARC Repair TP(CLSO)1 JOB CARD Sales Order: 5888852 JC NO305547999


OMER	REGN NO: SHD4781L	MILEAGE
s COMFORT TRANSPORTATION PTE LTD	MAKE: HYUNDAI	FUEL E.....1/2.....F
OMER NO. 7010045	MODEL IONIQ(G3)	DATE/TIME IN 09.03.2023 12:50
ESS 383 SIN MING DRIVE	YR OF MANU. 14.11.2019	TARGET DATE
Singapore SINGAPORE 575717	CHASSIS CODE KMHC851CVLU189928	COMPLETION DATE/TIME:
(R) 65508755 (O)		
(P)		
UNT CARD NO.		

icident Date: 09.03.2023
TURE: 3P 09.03.2023

NO LABOR CODE
0010 PB

JOB DESCRIPTION

DESCRIPTION
PANEL BEATING-SHD4781L-TP



ED & PASSED OUT BY:

SERVICE ADVISOR CUSTOMER'S SIGNATURE

dgement Slip	Exit Pass
Vehicle No.: SHD4781L	Vehicle No.: SHD4781L
Service Advisor	Name of Service Advisor
Signature/Date	Date
igned to Service Reception upon collection	To be kept by Security Guard