

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

ESTIMATE FOR SNJ1955U

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 62507388 Vehicle & Document Information

WIP No 63514

SNJ1955U / 28/12/2022

Date In/Mileage

Reg No/Reg Date

/ 0 W1N2477842J4518556

Chassis No Engine No

28291480925738

Make/Model

MB/GLA 180

Colour/Trim

026 667 Denim Blue / 046 651 Black

Account No	Terms	Date/Time Printed	CSE	Operator	363 Com			
WL001605	Credit	10/03/2023/ 08:57	K0	301 / Kerlyn Ong				
	era Basia	Description of Goo	ds / Services	Mag 1988, Kershall Harris	Qty	Unit Price	Disc%	Amount
M BPNSUN		NOT A		FFICIAL		XII	V	OICE
DRIVE IN	I∕TP VEHICL		08/03/2023 B // GBA706	8E -		2		
DATE IN/DATE SURVEY: BY/AUTHRIZED ON : A BPILAB								1920.00
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH. A BPIRES								1800.00
A BPILAB		PER & LH/ FRONT FENDE NOSTIC TO CHECK ON CO		RESET MEMORY TO	Feb.		0.10	380.00
IDENTIFI A BPILAB	ICATION STA	ANDARD. NETT	120	111100				120.00
M FRONT BU	JMPER	HEADLAMP WITH FOCUS			1.00 1.00	1479.47 71.44	00.00	1479.47 71.44
M LH/ FROM	NT BUMPER N NT FENDER 1	MOUNTING RAIL FRIM	and the same of th		1.00	9.33 227.85	00.00	9.33 227.85 20.58
M LH/ FROI	NT FENDER E DLAMP UNIT				1.00	20.58 3097.36	00.00	3097.36

Kerlyn Ong Kai Li

DID: 6771 4420 HP: 9186 5113

Email: kerlyn.ong@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

Confirmed & accepted by

Nett

9,126.03

8% GST on

9126.03

730.08

Total Payable

9,856.11

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6298 1818 Fax: 6779 5383 www.mercedes-benz.com.sg



SC2023390004 / CYCLE & CARRIAGE INDUSTRIES PTE LTD ENTRY DATE & TIME: 09/03/2023 18:01 (SGT) SUBMITTED BY: HELEN LEE VERSION: 1 (09/03/2023 18:01 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

DRIVER

NRIC No

Name of Driver

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

09/03/2023 18:01 (SGT) Date of Submission Reported by Owner Date of Accident 08/03/2023 22:25 (SGT) Exact Location of Accident Singapore ALONG PUNGGOL PARK OSCP Additional Location Information Country/State of Loss **DETAILS OF OWN VEHICLE** Vehicle Registration Number SNJ1955U INSURED/POLICYHOLDER Is company? Yes MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE PL Name Of Registered Owner Company Reg No 1XXXXX778Z KERLYN.ONG@CYCLECARRIAGE.COM.SG **Email Address** Mobile Phone No (Phone) +65-91865113 Alternative Phone No VEHICLE PARTICULARS Mercedes Manufacturer Gla180 Model Variant Exact purpose for which vehicle was being used at time of Private use accident Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Private car Vehicle Category Transmission Auto CC 1332 INSURANCE COMPANY Allianz Insurance Singapore Pte. Ltd. Name of Insurance Company Policy Number / Cover Note Number

TAY YUAN ZHUANG

SXXXX877Z

Date Of Driving Pass Driving experience Gender Mobile Number Alt. Phone Number Email Address Address Address Address complement Postcode Is the driver the policyholder? If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver	09/11/2004 18 YEARS AND 4 MONTHS Male (Phone) +65-81268782 - TAYYUANZHUANG@GMAIL.COM BLK 313C SUMANG LINK #14-141 822313 No Sibling No
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident Weather Conditions Road Surface	Hit and run / Vandalism / Damaged whilst parked Clear Dry
OTHER INFORMATION	
Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement	- -
DETAILS OF POLICE ACTION	
Was the accident reported to the police? Was notice of intended Prosecution given? If yes, against whom? CIRCUMSTANCES OF ACCIDENT	No No -
REFER TO ATTACHED	
ATTACHMENT(S)	
Are accident photos available for attachment? Was there any video captured by Car Camera? Reasons for not uploading a video of the accident	Yes Yes REFER CSE KERLYN
DETAILS OF OTHER	R VEHICLE PROPERTY 1
Vehicle Registration Number	GBA7068E

Matararala

Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour

Vahicle Category

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes in Li

 Kerlyn Ong Kai Li

 Kerlyn Ong Kai Li

 Company 186 5113

DID: 6771 4420 HP: 9186 5113


Email: kerlyn.ong@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time 09/03/2023 1616

Witnessed by Reporting Centre
Personnel KERLYN

Sketch Plan



I PARKED MY CAR (SNJ1955U) AT PUNNGOL PARK OSCP. I WAS SITTING INSIDE THE CAR AND WAS LOOKING AT MY PHONE.

VEHICLE B (GBA7068E) WAS DOING A REVERSING DID NOT NOTICE MY CAR AND COLLIDED ONTO MY LEFT PORTION.

Declaration

We declare the foregoing particulars are true in every respect.

Merlyn Ong Kai Li
DID: 6771 4420 HP: 91 5113

Email: kerlyn.ong@cyclecarrage.com.sg
Cycle & Carriage Industries Pie Lid
Customer Service Centre - Pandan Loop

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time 09/03/2023 1616

Witnessed by Reporting Centre Personnel KERLYN