

REF:

From: _____ Date: _____

Veh No: SLV46K. Yr Regn: 2016 / Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Civic C.C. 1488

Colour white. A/C: Insured / Std / NI / NA

Sp. Reading 115617. T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRH FC1660GT000346

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modif: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50R16.

R: 025/50416.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 03 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 22/02/23

*Survey held at J-Mart.

Des. of Damages : Frt / **Rear** / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time. File Pass to?

☐ : Prel. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech Insp (\$ _____)
☐ : _____ (\$ _____)

Survey Fee:

Transportation:

$$S + RS \rightarrow S$$

Photos

Cybers